



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,486,298
Version:	1
Created:	20 Dec 2023

Make:	Nissan	Body Style:	Van
Model:	NV350	VIN:	7AT0DH8RX23037174
Year:	2016	Odometer:	30,556 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good				
4	High Stop Light	✓	Transmission and Drive		59	Steering Performance	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good				
5	Front Right Indicators	✓	34	Operation	✓ <th colspan="2">Wheels and Tyres</th> <td>61</td> <td>Left Front</td> <td>6.0</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		61	Left Front	6.0	mm	85	R/H Mirror	Good			
6	Front Left Indicators	✓	35	Noise	✓ <td>62</td> <td>Right Front</td> <td>6.0</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>5.0</td> <td>mm</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	62	Right Front	6.0	mm	63	Left Rear	5.0	mm	86	L/H Mirror	Good	
7	Rear Right Indicators	✓	36	Clutch	•	64	Right Rear	5.0	mm	65	Spare	Yes	87	L/F Guard	Good		
8	Rear Left Indicators	✓	37	CV Joints	•	66	Tools	✓	67	AC Operation	✓ <td>88</td> <td>R/F Guard</td> <td>Good</td>	88	R/F Guard	Good			
9	Reversing Lights	✓	38	Wheel Bearing	✓ <th colspan="2">Interior</th> <td>68</td> <td>Heater Fan</td> <th>✓<td>69</td><td>Seatbelts</td><th>✓<td>89</td><td>L/H Doors</td><td>Good</td></th></th>	Interior		68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>89</td><td>L/H Doors</td><td>Good</td></th>	69	Seatbelts	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td>	89	L/H Doors	Good	
10	Rear Reflectors	✓	39	Wheel Balance	✓ <td>70</td> <td>Horn</td> <th>✓<td>71</td><td>Seat Heaters</td><td>•</td><td>72</td><td>Sun Visors</td><th>✓<td>90</td><td>R/H Doors</td><td>Good</td></th></th>	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>72</td> <td>Sun Visors</td> <th>✓<td>90</td><td>R/H Doors</td><td>Good</td></th>	71	Seat Heaters	•	72	Sun Visors	✓ <td>90</td> <td>R/H Doors</td> <td>Good</td>	90	R/H Doors	Good
11	Hazard Lights	✓	40	Gearbox (Manual)	•	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Average</td> <td>75</td> <td>Carpets</td> <td>Average</td> <td>91</td> <td>L/H Sill</td> <td>Good</td>	74	Seats	Average	75	Carpets	Average	91	L/H Sill	Good
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	76	Panels	Average	77	Dashboard	Average	92	R/H Sill	Good	93	Boot/Tail Gate	Good
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good
14	Dashboard Dimmer Switch	•	43	Replaced at (odometer reading)		98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓			
15	Number Plate Light	✓	Brakes		99	Turners Certification Key:											
16	Dashboard Warning Lights	✓	44	Front Brakes	✓ <td>✓ = Pass</td> <td colspan="8"></td>	✓ = Pass											
17	Speedo	✓	45	Rear Brakes	✓ <td>×</td> <td>Fail</td> <td colspan="8"></td>	×	Fail										
18	Odometer	✓	46	Handbrake	✓	•	Not applicable for this vehicle										
19	Rev Counter	✓	Keys and Locking		99	Turners Certification Key:											
20	Fuel Gauge	✓	47	Central Locking	✓	✓ = Pass											
21	Wipers Front/Rear	✓	48	Remote Locking	✓	×	Fail										
22	Window Opener FL	✓	49	Number of Keys	1	•	Not applicable for this vehicle										
23	Window Opener FR	✓	Engine		99	Turners Certification Key:											
24	Window Opener RL	•	50	Oil Level	✓	✓ = Pass											
25	Window Opener RR	•	51	Smokes and Fumes	✓	×	Fail										
26	Rear View Mirrors	✓	52	Performance	✓	•	Not applicable for this vehicle										
27	Radio (Basic Test Only)	✓	53	Noise	✓	✓ = Pass											
28	CD (Basic Test Only)	•	54	Starter Motor	✓	×	Fail										
29	Boot Open Switch	✓				•	Not applicable for this vehicle										

Inspected by:	Greg Morgan	Date:	18 Dec 2023
<b>I have read and understood this condition guide:</b>			
Name:		Signature:	