



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,486,401
Version:	1
Created:	28 Dec 2023

Make:	Lexus	Body Style:	
Model:	CT200H	VIN:	
Year:	2012	Odometer:	101,505 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good							
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•									
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good										
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	81	Back Windscreen (no chips)	Good								
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	82	Side Windows (no chips)	Good								
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	83	Front Wiper Blades	Good										
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	3.5	mm	84	Rear Wiper Blade	Good							
7	Rear Right Indicators	✓	37	CV Joints	✓	62	Right Front	4	mm	63	Left Rear	4	mm	85	R/H Mirror	Good					
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	64	Right Rear	4	mm	65	Spare	N/A	66	Tools	✓	86	L/H Mirror	Good			
9	Reversing Lights	✓	39	Wheel Balance	✓	40		Gearbox (Manual)	•	Interior <td>67</td> <td>AC Operation</td> <th>✓</th> <td>68</td> <td>Heater Fan</td> <th>✓</th> <td>87</td> <td>L/F Guard</td> <td>Good</td>		67	AC Operation	✓	68	Heater Fan	✓	87	L/F Guard	Good	
10	Rear Reflectors	•	41	Engine Timing	Timing Chain	42	Evidence of Cam Belt Replacement	Not Applicable	43	Replaced at (odometer reading)		69	Seatbelts	✓	70	Horn	✓	88	R/F Guard	Good	
11	Hazard Lights	✓	44		Brakes	45	Front Brakes	✓	46		Handbrake	✓	71	Seat Heaters	✓	72	Sun Visors	✓	89	L/H Doors	Good
12	Courtesy Lights	•	47		Keys and Locking	48	Remote Locking	✓	49		Number of Keys	1	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	90	R/H Doors	Good
13	Dashboard Lights	✓	48		Engine	50	Oil Level	✓	51		Smokes and Fumes	✓	75	Carpets	Good	76	Panels	Good	91	L/H Sill	Good
14	Dashboard Dimmer Switch	✓	52		Performance	✓	53	Noise	✓	54		Starter Motor	✓	77	Dashboard	Good			92	R/H Sill	Good
15	Number Plate Light	✓	53		Noise	✓												93	Boot/Tail Gate	Good	
16	Dashboard Warning Lights	✓	54		Starter Motor	✓												94	Front Bumper	Good	
17	Speedo	✓																95	Rear Bumper	Good	
18	Odometer	✓																96	Roof	Good	
19	Rev Counter	•																97	Bonnet	Good	
20	Fuel Gauge	✓																98	Fuel Cap	✓	
21	Wipers Front/Rear	✓																99	Mud Flaps	✓	
22	Window Opener FL	✓																100	WOF	✓	
23	Window Opener FR	✓																			
24	Window Opener RL	✓																			
25	Window Opener RR	✓																			
26	Rear View Mirrors	✓																			
27	Radio (Basic Test Only)	✓																			
28	CD (Basic Test Only)	✓																			
29	Boot Open Switch	✓																			

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:
✓ = Pass
× = Fail
• = Not applicable for this vehicle

Inspected by:	Blair Robertson	Date:	28 Dec 2023
I have read and understood this condition guide:			
Name:		Signature:	