



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,486,438
Version:	2
Created:	13 Mar 2024

Make:	Mitsubishi	Body Style:	Wagon
Model:	Outlander	VIN:	7AT0CJ3MX23700825
Year:	2019	Odometer:	65,770 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•					
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good						
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good				
4	High Stop Light	✓	Transmission and Drive		59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good				
5	Front Right Indicators	✓	34	Operation	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good						
6	Front Left Indicators	✓	35	Noise	✓ <th colspan="2">Wheels and Tyres</th> <td>61</td> <td>Left Front</td> <td>5.5</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		61	Left Front	5.5	mm	85	R/H Mirror	Good			
7	Rear Right Indicators	✓	36	Clutch	•	62	Right Front	5.5	mm	63	Left Rear	5.5	mm	86	L/H Mirror	Good	
8	Rear Left Indicators	✓	37	CV Joints	✓ <td>64</td> <td>Right Rear</td> <td>5.5</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>N/A</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	64	Right Rear	5.5	mm	65	Spare	N/A	87	L/F Guard	Good		
9	Reversing Lights	✓	38	Wheel Bearing	✓ <td>66</td> <td>Tools</td> <th>✓<td>67</td><td>AC Operation</td><th>✓<td>88</td><td>R/F Guard</td><td>Good</td></th></th>	66	Tools	✓ <td>67</td> <td>AC Operation</td> <th>✓<td>88</td><td>R/F Guard</td><td>Good</td></th>	67	AC Operation	✓ <td>88</td> <td>R/F Guard</td> <td>Good</td>	88	R/F Guard	Good			
10	Rear Reflectors	✓	39	Wheel Balance	✓ <th colspan="2">Interior</th> <td>68</td> <td>Heater Fan</td> <th>✓<td>69</td><td>Seatbelts</td><th>✓<td>89</td><td>L/H Doors</td><td>Good</td></th></th>	Interior		68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>89</td><td>L/H Doors</td><td>Good</td></th>	69	Seatbelts	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td>	89	L/H Doors	Good	
11	Hazard Lights	✓	40	Gearbox (Manual)	•	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <th>✓<td>72</td><td>Sun Visors</td><th>✓<td>90</td><td>R/H Doors</td><td>Good</td></th></th>	71	Seat Heaters	✓ <td>72</td> <td>Sun Visors</td> <th>✓<td>90</td><td>R/H Doors</td><td>Good</td></th>	72	Sun Visors	✓ <td>90</td> <td>R/H Doors</td> <td>Good</td>	90	R/H Doors	Good
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td>91</td> <td>L/H Sill</td> <td>Good</td>	74	Seats	Good	75	Carpets	Good	91	L/H Sill	Good
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	76	Panels	Good	77	Dashboard	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good
15	Number Plate Light	✓	Brakes		98	Fuel Cap	✓ <td>99</td> <td>Mud Flaps</td> <th>✓<td>100</td><td>WOF</td><th>✓</th></th>	99	Mud Flaps	✓ <td>100</td> <td>WOF</td> <th>✓</th>	100	WOF	✓				
16	Dashboard Warning Lights	✓	44	Front Brakes	✓ <td>99</td> <td>Mud Flaps</td> <th>✓</th>	99	Mud Flaps	✓									
17	Speedo	✓	45	Rear Brakes	✓ <td></td> <td></td> <td></td>												
18	Odometer	✓	46	Handbrake	✓ <td></td> <td></td> <td></td>												
19	Rev Counter	•	Keys and Locking														
20	Fuel Gauge	✓	47	Central Locking	✓ <td></td> <td></td> <td></td>												
21	Wipers Front/Rear	✓	48	Remote Locking	✓ <td></td> <td></td> <td></td>												
22	Window Opener FL	✓	49	Number of Keys	1												
23	Window Opener FR	✓	Engine														
24	Window Opener RL	✓	50	Oil Level	✓ <td></td> <td></td> <td></td>												
25	Window Opener RR	✓	51	Smokes and Fumes	✓ <td></td> <td></td> <td></td>												
26	Rear View Mirrors	✓	52	Performance	✓ <td></td> <td></td> <td></td>												
27	Radio (Basic Test Only)	✓	53	Noise	✓ <td></td> <td></td> <td></td>												
28	CD (Basic Test Only)	•	54	Starter Motor	✓ <td></td> <td></td> <td></td>												
29	Boot Open Switch	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>															

Turners Certification Key:
✓ = Pass
× = Fail
• = Not applicable for this vehicle

Inspected by:	Blair Robertson	Date:	13 Mar 2024
I have read and understood this condition guide:			
Name:		Signature:	