



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,486,781
Version:	1
Created:	22 Jan 2024

Make:	Subaru	Body Style:	Wagon
Model:	Impreza	VIN:	7AT0GF09X24083514
Year:	2014	Odometer:	45,782 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good								
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good								
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good								
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good						
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	85	R/H Mirror	Good	86	L/H Mirror	Good						
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	61	Left Front	7.5	mm	87	L/F Guard	Good	88	R/F Guard	Good				
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		62	Right Front	7.5	mm	89	L/H Doors	Good	90	R/H Doors	Good					
7	Rear Right Indicators	✓	37	CV Joints	✓	63	Left Rear	7	mm	64	Right Rear	7	mm	91	L/H Sill	Good	92	R/H Sill	Good			
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	65	Spare	N/A	66	Tools	✓	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓	Interior		67	AC Operation	✓	68	Heater Fan	✓	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	•	99	Mud Flaps	✓	100	WOF	✓		
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good								
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good								
13	Dashboard Lights	✓	43	Replaced at (odometer reading)																		
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓															
15	Number Plate Light	✓	45	Rear Brakes	✓																	
16	Dashboard Warning Lights	✓	46	Handbrake	✓																	
17	Speedo	✓	Keys and Locking		47	Central Locking	✓															
18	Odometer	✓	48	Remote Locking	✓	49	Number of Keys	1														
19	Rev Counter	✓	Engine		50	Oil Level	✓															
20	Fuel Gauge	✓	51	Smokes and Fumes	✓	52	Performance	✓														
21	Wipers Front/Rear	✓	53	Noise	✓	54	Starter Motor	✓														
22	Window Opener FL	✓																				
23	Window Opener FR	✓																				
24	Window Opener RL	✓																				
25	Window Opener RR	✓																				
26	Rear View Mirrors	✓																				
27	Radio (Basic Test Only)	✓																				
28	CD (Basic Test Only)	✓																				
29	Boot Open Switch	✓																				

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Dean Sinclair	Date:	22 Jan 2024
---------------	---------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--