



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID: 24,486,799

Version: 1

Created: 23 Jan 2024

Make:	Mazda	Body Style:	Wagon
Model:	CX-5	VIN:	7AT0C144X23300408
Year:	2018	Odometer:	75,767 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good				
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation				•				
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good				
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good		
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td><td>85</td><td>R/H Mirror</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	84	Rear Wiper Blade	Good	85	R/H Mirror	Good		
5	Front Right Indicators	✓	35	Noise	✓ <td>36</td> <td>Clutch</td> <td>•</td> <td>60</td> <td>Shock Absorbers</td> <th>✓<td>86</td><td>L/H Mirror</td><td>Good</td><td>87</td><td>L/F Guard</td><td>Good</td></th>	36	Clutch	•	60	Shock Absorbers	✓ <td>86</td> <td>L/H Mirror</td> <td>Good</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	86	L/H Mirror	Good	87	L/F Guard	Good	
6	Front Left Indicators	✓	37	CV Joints	✓ <td>38</td> <td>Wheel Bearing</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>61</td><td>Left Front</td><td>7.5</td><td>mm</td><td>88</td><td>R/F Guard</td><td>Good</td></th>	38	Wheel Bearing	✓ <th colspan="2">Wheels and Tyres</th> <td>61</td> <td>Left Front</td> <td>7.5</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	Wheels and Tyres		61	Left Front	7.5	mm	88	R/F Guard	Good	
7	Rear Right Indicators	✓	39	Wheel Balance	✓ <td>39</td> <td>Wheel Balance</td> <th>✓<td>62</td><td>Right Front</td><td>7.5</td><td>mm</td><td>89</td><td>L/H Doors</td><td>Good</td><td>90</td><td>R/H Doors</td><td>Good</td></th>	39	Wheel Balance	✓ <td>62</td> <td>Right Front</td> <td>7.5</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	62	Right Front	7.5	mm	89	L/H Doors	Good	90	R/H Doors	Good
8	Rear Left Indicators	✓	40	Gearbox (Manual)	•	41	Engine Timing	Timing Chain	63	Left Rear	7.5	mm	91	L/H Sill	Good	92	R/H Sill	Good
9	Reversing Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	42	Evidence of Cam Belt Replacement	Not Applicable	64	Right Rear	7.5	mm	93	Boot/Tail Gate	Good	94	Front Bumper	Good
10	Rear Reflectors	✓	43	Replaced at (odometer reading)		43	Replaced at (odometer reading)		65	Spare	N/A		95	Rear Bumper	Good	96	Roof	Good
11	Hazard Lights	✓	Brakes		44	Front Brakes	✓ <th colspan="2">Interior</th> <td>66</td> <td>Tools</td> <th>✓<td>97</td><td>Bonnet</td><td>Good</td><td>98</td><td>Fuel Cap</td><th>✓</th></th>	Interior		66	Tools	✓ <td>97</td> <td>Bonnet</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	97	Bonnet	Good	98	Fuel Cap	✓
12	Courtesy Lights	✓	45	Rear Brakes	✓ <td>45</td> <td>Rear Brakes</td> <th>✓<td>67</td><td>AC Operation</td><th>✓<td>99</td><td>Mud Flaps</td><th>✓</th><td>100</td><td>WOF</td><th>✓</th></th></th>	45	Rear Brakes	✓ <td>67</td> <td>AC Operation</td> <th>✓<td>99</td><td>Mud Flaps</td><th>✓</th><td>100</td><td>WOF</td><th>✓</th></th>	67	AC Operation	✓ <td>99</td> <td>Mud Flaps</td> <th>✓</th> <td>100</td> <td>WOF</td> <th>✓</th>	99	Mud Flaps	✓	100	WOF	✓	
13	Dashboard Lights	✓	46	Handbrake	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>68</td><td>Heater Fan</td><th>✓<td></td><td></td><td></td><td></td><td></td><td></td></th></th>	46	Handbrake	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td></td><td></td><td></td><td></td><td></td><td></td></th>	68	Heater Fan	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>							
14	Dashboard Dimmer Switch	✓	Keys and Locking		47	Central Locking	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td></td><td></td><td></td><td></td><td></td><td></td><td></td></th>	69	Seatbelts	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
15	Number Plate Light	✓	48	Remote Locking	✓ <td>48</td> <td>Remote Locking</td> <th>✓<td>70</td><td>Horn</td><th>✓<td></td><td></td><td></td><td></td><td></td><td></td></th></th>	48	Remote Locking	✓ <td>70</td> <td>Horn</td> <th>✓<td></td><td></td><td></td><td></td><td></td><td></td></th>	70	Horn	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>							
16	Dashboard Warning Lights	✓	49	Number of Keys	1	49	Number of Keys	1	71	Seat Heaters	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>							
17	Speedo	✓	Engine		50	Oil Level	✓ <td>72</td> <td>Sun Visors</td> <th>✓<td></td><td></td><td></td><td></td><td></td><td></td><td></td></th>	72	Sun Visors	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
18	Odometer	✓	51	Smokes and Fumes	✓ <td>51</td> <td>Smokes and Fumes</td> <th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td></td><td></td><td></td><td></td><td></td><td></td></th></th>	51	Smokes and Fumes	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td></td><td></td><td></td><td></td><td></td><td></td></th>	73	Sun Visors Lights/Mirrors	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>							
19	Rev Counter	✓	52	Performance	✓ <td>52</td> <td>Performance</td> <th>✓<td>74</td><td>Seats</td><td>Good</td><td></td><td></td><td></td><td></td><td></td><td></td></th>	52	Performance	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	74	Seats	Good							
20	Fuel Gauge	✓	53	Noise	✓ <td>53</td> <td>Noise</td> <th>✓<td>75</td><td>Carpets</td><td>Good</td><td></td><td></td><td></td><td></td><td></td><td></td></th>	53	Noise	✓ <td>75</td> <td>Carpets</td> <td>Good</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	75	Carpets	Good							
21	Wipers Front/Rear	✓	54	Starter Motor	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>76</td><td>Panels</td><td>Good</td><td></td><td></td><td></td><td></td><td></td><td></td></th>	54	Starter Motor	✓ <td>76</td> <td>Panels</td> <td>Good</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	76	Panels	Good							
22	Window Opener FL	✓							77	Dashboard	Good							
23	Window Opener FR	✓																
24	Window Opener RL	✓																
25	Window Opener RR	✓																
26	Rear View Mirrors	✓																
27	Radio (Basic Test Only)	✓																
28	CD (Basic Test Only)	•																
29	Boot Open Switch	✓																

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Dean Sinclair	Date:	23 Jan 2024
I have read and understood this condition guide:			
Name:		Signature:	