

Basic Vehicle Condition Guide

Report ID: 24,487,259


Version: 1

Created: 10 Nov 2023

Make: Model: Mercedes-Benz Vito **Body Style:** People Mover Year: 2006 Registration: DHZ927 Reg Expiry: 10 Jan 2024 WoF Expiry: **Odometer:** 24 Oct 2024 181,445 Kms **Good No:** 24487259 VIN: WDF63960323192759 Next Service: 0 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Rust inside tailgate bottom interior lip by latch,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	centre console modified, rear of van modified ,		
Dashboard	Average		

General Comments

Drives okay,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara Date:

Name:

	Pass	Fail	N/A
Engine	1 433	T GII	14//
Oil level	V		
Smoke & fumes	<i>'</i>		
Performance	\(\times \)		
Noise	<i>y</i>		
Cooling System	_		
Coolant condition	V		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front			mm
Right front	4		mm
Left rear	3		mm
Right rear	3		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	\(\times \)		
Shock absorbers	~		
Air Conditioning / Heater		ļ	
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	V V		
Dashboard warning lights			
Wipers (front & rear)	\(\triangle \)		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1	1	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		
-			

10 Nov 2023

Signature: