

Report ID: 24,490,458 Version: 1 02 Apr 2024 Created:

Make:	Suzuki	Model:	Ignis	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2018	Registration:	QAY258	Reg Expiry:	25 Jun 2024	Engine			1
	05 Apr 2024	Odometer:	35,361 Kms	Good No:	24490458	Oil level	~		
VIN:	7AT0GKDTX23140829	Next Service:	45,000	Service Histor	y: No	Smoke & fumes	~		
					-	Performance		~	
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~	-	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0	LW	-161-	P W	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect C = crack P = pin dent						Transmission	•		
						Operation	~		
						Noise	~		
						Clutch			~
						CV joints	~		
* = decals SC PIP						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SC S SC W P SC W W									
							~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Hand Brake		
						Tyres (lowest observed tread depth of tyres)			
						Left front		5 mm	
						Right front	5 mm		-
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
Under Corrigge & Under Despetition Comments						Spare No			
Under Carriage & Under Bonnet Inspection Comments						Suspension	1		-
Front whee	l drive,					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments Good Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashte	Good					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
	_					Window winder FR	~		
General Comments						Window winder RL	~		
Vehicle not	switching into "EV" mo	de or using batte	ery assistance.			Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	V		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							1		1
Inspected by: Andre Richardson Date: 02 Apr 2024									
I have read and understood this condition guide. Name:									