



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,498,716
Version:	1
Created:	17 Jan 2024

Make:	Lexus	Body Style:	Hatchback
Model:	CT200H	VIN:	7AT0B010X23016988
Year:	2011	Odometer:	76,935 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30 Fuel Flap Release		Cooling System		Exterior	
1	Battery	✓	✓	55	Coolant Condition	✓	78 Under Carriage Good
2	Headlights	✓	✓	56	Performance	✓	79 Sun Roof Operation <input type="checkbox"/>
3	Tail Lights	✓	✓	57	Radiator/Hoses (visual)	✓	80 Front Windscreen (no chips) Good
4	High Stop Light	✓	✓	Suspension		81 Back Windscreen (no chips) Good	
5	Front Right Indicators	✓	✓	58	Suspension Performance	✓	82 Side Windows (no chips) Good
6	Front Left Indicators	✓	✓	59	Steering Performance	✓	83 Front Wiper Blades Good
7	Rear Right Indicators	✓	✓	60	Shock Absorbers	✓	84 Rear Wiper Blade Good
8	Rear Left Indicators	✓	✓	Wheels and Tyres		85 R/H Mirror Good	
9	Reversing Lights	✓	✓	61	Left Front	5.0 mm	86 L/H Mirror Good
10	Rear Reflectors	✓	✓	62	Right Front	5.0 mm	87 L/F Guard Good
11	Hazard Lights	✓	✓	63	Left Rear	5.0 mm	88 R/F Guard Good
12	Courtesy Lights	✓	✓	64	Right Rear	5.0 mm	89 L/H Doors Good
13	Dashboard Lights	✓	✓	65	Spare	N/A	90 R/H Doors Good
14	Dashboard Dimmer Switch	✓	✓	66	Tools	✓	91 L/H Sill Good
15	Number Plate Light	✓	✓	Interior		92 R/H Sill Good	
16	Dashboard Warning Lights	✓	✓	67	AC Operation	✓	93 Boot/Tail Gate Good
17	Speedo	✓	✓	68	Heater Fan	✓	94 Front Bumper Good
18	Odometer	✓	✓	69	Seatbelts	✓	95 Rear Bumper Good
19	Rev Counter	✓	✓	70	Horn	✓	96 Roof Good
20	Fuel Gauge	✓	✓	71	Seat Heaters	<input type="checkbox"/>	97 Bonnet Good
21	Wipers Front/Rear	✓	✓	72	Sun Visors	✓	98 Fuel Cap <input type="checkbox"/>
22	Window Opener FL	✓	✓	73	Sun Visors Lights/Mirrors	✓	99 Mud Flaps <input type="checkbox"/>
23	Window Opener FR	✓	✓	74	Seats	Average	100 WOF <input type="checkbox"/>
24	Window Opener RL	✓	✓	75	Carpets	Average	
25	Window Opener RR	✓	✓	76	Panels	Average	
26	Rear View Mirrors	✓	✓	77	Dashboard	Average	
27	Radio (Basic Test Only)	✓	✓	Transmission and Drive			
28	CD (Basic Test Only)	<input type="checkbox"/>	✓	34	Operation	✓	
29	Boot Open Switch	✓	✓	35	Noise	✓	
				36	Clutch	<input type="checkbox"/>	
				37	CV Joints	✓	
				38	Wheel Bearing	✓	
				39	Wheel Balance	✓	
				40	Gearbox (Manual)	<input type="checkbox"/>	
				41	Engine Timing	Timing Chain	
				42	Evidence of Cam Belt Replacement	Not Applicable	
				43	Replaced at (odometer reading)		
				Brakes			
				44	Front Brakes	✓	
				45	Rear Brakes	✓	
				46	Handbrake	✓	
				Keys and Locking			
				47	Central Locking	✓	
				48	Remote Locking	✓	
				49	Number of Keys	1	
				Engine			
				50	Oil Level	✓	
				51	Smokes and Fumes	✓	
				52	Performance	✓	
				53	Noise	✓	
				54	Starter Motor	✓	

Turners Certification Key:
 ✓ = Pass
 X = Fail
 • = Not applicable for this vehicle

Inspected by:	Greg Morgan	Date:	09 Jan 2024
---------------	-------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--