



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,498,771
Version:	1
Created:	20 Dec 2023

Make:	Toyota	Body Style:	Hatchback
Model:	Vitz	VIN:	7AT0H63EX23040506
Year:	2018	Odometer:	58,193 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good					
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good					
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good					
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good						
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good						
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	Wheels and Tyres		85	R/H Mirror	Good						
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	7.0	mm	86	L/H Mirror	Good							
7	Rear Right Indicators	✓	37	CV Joints	✓	62	Right Front	7.0	mm	87	L/F Guard	Good							
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	63	Left Rear	7.0	mm	88	R/F Guard	Good							
9	Reversing Lights	✓	39	Wheel Balance	✓	64	Right Rear	7.0	mm	89	L/H Doors	Good							
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	65	Spare	N/A	90	R/H Doors	Good								
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	66	Tools	✓	91	L/H Sill	Good								
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	Interior		67	AC Operation	✓	92	R/H Sill	Good						
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		68	Heater Fan	•	69	Seatbelts	✓	93	Boot/Tail Gate	Good					
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓	70	Horn	✓	71	Seat Heaters	•	94	Front Bumper	Good			
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	95	Rear Bumper	Good		
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓	74	Seats	Average	75	Carpets	Average	76	Panels	Average	77	Dashboard	Average
17	Speedo	✓	48	Remote Locking	✓	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓
18	Odometer	✓	49	Number of Keys	1	54	Starter Motor	✓	55	CD (Basic Test Only)	•	56	Boot Open Switch	✓					
19	Rev Counter	✓																	
20	Fuel Gauge	✓																	
21	Wipers Front/Rear	✓																	
22	Window Opener FL	✓																	
23	Window Opener FR	✓																	
24	Window Opener RL	✓																	
25	Window Opener RR	✓																	
26	Rear View Mirrors	✓																	
27	Radio (Basic Test Only)	✓																	
28	CD (Basic Test Only)	•																	
29	Boot Open Switch	✓																	

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:
✓ = Pass
× = Fail
• = Not applicable for this vehicle

Inspected by:	Greg Morgan	Date:	18 Dec 2023
I have read and understood this condition guide:			
Name:		Signature:	