



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,512,031
Version:	2
Created:	02 Feb 2024

Make:	Subaru	Body Style:	Wagon
Model:	Levorg	VIN:	7AT0GF22X23008045
Year:	2014	Odometer:	90,223 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good						
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•								
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good									
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good							
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good							
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>61</td><td>Left Front</td><td>6.0</td><td>mm</td><td>83</td><td>Front Wiper Blades</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>61</td> <td>Left Front</td> <td>6.0</td> <td>mm</td> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	61	Left Front	6.0	mm	83	Front Wiper Blades	Good					
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		62	Right Front	6.0	mm	84	Rear Wiper Blade	Good						
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>63</td> <td>Left Rear</td> <td>6.0</td> <td>mm</td> <td>64</td> <td>Right Rear</td> <td>6.0</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	63	Left Rear	6.0	mm	64	Right Rear	6.0	mm	85	R/H Mirror	Good				
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>65</td> <td>Spare</td> <td>N/A</td> <td>66</td> <td>Tools</td> <th>✓</th> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	65	Spare	N/A	66	Tools	✓	86	L/H Mirror	Good						
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>67</td> <td>AC Operation</td> <th>✓<td>68</td><td>Heater Fan</td><th>✓<td>87</td><td>L/F Guard</td><td>Good</td></th></th>	67	AC Operation	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>87</td><td>L/F Guard</td><td>Good</td></th>	68	Heater Fan	✓ <td>87</td> <td>L/F Guard</td> <td>Good</td>	87	L/F Guard	Good						
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	69	Seatbelts	✓ <td>70</td> <td>Horn</td> <th>✓<td>88</td><td>R/F Guard</td><td>Good</td></th>	70	Horn	✓ <td>88</td> <td>R/F Guard</td> <td>Good</td>	88	R/F Guard	Good						
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	71	Seat Heaters	•	72	Sun Visors	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td>	89	L/H Doors	Good						
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Average</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	74	Seats	Average	90	R/H Doors	Good						
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		75	Carpets	Average	76	Panels	Average	91	L/H Sill	Good						
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>77</td> <td>Dashboard</td> <td>Average</td> <td>92</td> <td>R/H Sill</td> <td>Good</td>	77	Dashboard	Average	92	R/H Sill	Good							
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<th colspan="2">Interior</th><td>67</td><td>AC Operation</td><th>✓<td>93</td><td>Boot/Tail Gate</td><td>Good</td></th></th>	46	Handbrake	✓ <th colspan="2">Interior</th> <td>67</td> <td>AC Operation</td> <th>✓<td>93</td><td>Boot/Tail Gate</td><td>Good</td></th>	Interior		67	AC Operation	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	93	Boot/Tail Gate	Good				
16	Dashboard Warning Lights	✓	47	Central Locking	✓ <th colspan="2">Keys and Locking</th> <td>68</td> <td>Heater Fan</td> <th>✓<td>69</td><td>Seatbelts</td><th>✓<td>94</td><td>Front Bumper</td><td>Good</td></th></th>	Keys and Locking		68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>94</td><td>Front Bumper</td><td>Good</td></th>	69	Seatbelts	✓ <td>94</td> <td>Front Bumper</td> <td>Good</td>	94	Front Bumper	Good				
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td>69</td> <td>Seatbelts</td> <th>✓<td>70</td><td>Horn</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th></th>	49	Number of Keys	2	69	Seatbelts	✓ <td>70</td> <td>Horn</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th>	70	Horn	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td>	95	Rear Bumper	Good			
18	Odometer	✓	Engine		50	Oil Level	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>72</td> <td>Sun Visors</td> <th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>96</td><td>Roof</td><td>Good</td></th></th>	71	Seat Heaters	•	72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>96</td><td>Roof</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>96</td> <td>Roof</td> <td>Good</td>	96	Roof	Good	
19	Rev Counter	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>74</td><td>Seats</td><td>Average</td><td>75</td><td>Carpets</td><td>Average</td><td>76</td><td>Panels</td><td>Average</td><td>97</td><td>Bonnet</td><td>Good</td></th>	52	Performance	✓ <td>74</td> <td>Seats</td> <td>Average</td> <td>75</td> <td>Carpets</td> <td>Average</td> <td>76</td> <td>Panels</td> <td>Average</td> <td>97</td> <td>Bonnet</td> <td>Good</td>	74	Seats	Average	75	Carpets	Average	76	Panels	Average	97	Bonnet	Good
20	Fuel Gauge	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>77</td><td>Dashboard</td><td>Average</td><td>78</td><td>Under Carriage</td><td>Good</td><td>79</td><td>Sun Roof Operation</td><td>•</td><td>98</td><td>Fuel Cap</td><th>✓</th></th>	54	Starter Motor	✓ <td>77</td> <td>Dashboard</td> <td>Average</td> <td>78</td> <td>Under Carriage</td> <td>Good</td> <td>79</td> <td>Sun Roof Operation</td> <td>•</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	77	Dashboard	Average	78	Under Carriage	Good	79	Sun Roof Operation	•	98	Fuel Cap	✓
21	Wipers Front/Rear	✓										80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good
22	Window Opener FL	✓										83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good
23	Window Opener FR	✓										86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good
24	Window Opener RL	✓										89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good
25	Window Opener RR	✓										92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good
26	Rear View Mirrors	✓										95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good
27	Radio (Basic Test Only)	✓										98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓
28	CD (Basic Test Only)	•																		
29	Boot Open Switch	✓																		

Turners Certification Key:
✓ = Pass
× = Fail
• = Not applicable for this vehicle

Inspected by:	Greg Morgan	Date:	29 Dec 2023
I have read and understood this condition guide:			
Name:		Signature:	