

Report ID: 24,848,072 6 Version: 21 Mar 2025 Created:

Make:	LDV	Model:	V80	Body Style:	Van		Pass	Fail	N/A
Year:	2018	Registration:	LQL335	Reg Expiry:	26 Aug 2025	Engine	I	L	1
WoF Expiry:		Odometer:	77,250 Kms	Good No:	24848072	Oil level	~		
VIN:	LSH14JTC6JA083837	Next Service:	87,237	Service Histor	y: No	Smoke & fumes	~		+
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		+
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	S SC W	<u>~</u> ⊘	S SC W	-M-		Radiator / Hoses (visual)	~		-
S = scratch						Transmission	ssion		
D = dent						Operation	~		Τ
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		-
* = decals S SC W Q Q						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs D SC W S W S SC W						Performance			
Note come defects ? blamiches may not be displayed in the displayer						Hand Brake	~		+
Body Inspection Comments						Tyres (lowest observed tread	·		
LH/R mag wheel missing									
Aftermarket box & tail lift fitted to rear						Right front	9.0		mm
						Left rear	8		mm
Conditions During Pody Inspections						Right rear			 mm
Conditions During Body Inspection: Dry						Spare	3.0 mn No		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
<u></u>					Suspension performance	~		T	
Front wheel drive Note:- Vehicle too big to lift on hoist						Steering performance	~		
Note:- veri	cie too big to int on noi	SL				Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			T
Interior Comments						Electrical / Accessories		~	
						Head lights			T
Seats	Average					Tail lights	~		
Carpets	Good						~		
							~		+
Panels	Good					Dashboard warning lights	V		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	~		
							~		
General (omments					Window winder FR	~		+
General Comments						Window winder RL			~
Air-con not cold, Reverse camera not working correctly, Navigation not working, Lifter doesn't work, Roller door damaged,						Window winder RR			~
Steering pulls to the right - needs a wheel alignment						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		_	~
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Ti	ming Mechanism:	Timing	Chain			Remote locking	~		
						Sat. Nav. (basic test only)		~	
Lvidence		cinent. p	lot Applicable	11115.		Reversing camera		~	
Inspected by: My Autoshop						Date: 18 Feb 2025			
I have read and understood this condition guide. Name:									