

Report ID:	24,876,633	Version:	1
Created:	15 Apr 2026		


Make:	Holden	Model:	Equinox
Body Style:	SUV	Year:	2020
Rego No.:	NEM623	Rego Expiry:	02 Dec 2026
WoF Expiry:	18 Dec 2026	Odometer:	183,767 Kms
Good No.:	24876633	VIN:	3G0AX7EX1LS687787
Next Service:	197,000km's	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Holes in left and right side corners on front & rear bumpers. Rubber dome with wires in it fitted to roof panel, they were the wires that went to light bar. Two R/T aerial bases fitted to roof panel. Three bolt holes in left front foot well area.

Conditions During Body Inspection: Wet Dry

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Screw holes in dashboard & left side of centre console. Driver's door frame seal is torn & damaged. Non-factory base board fitted in boot floor. Interior roof sun glasses storage pocket is missing. Metal plate fitted to top of dashboard. Hole in carpet in right front foot well area.

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No

Inspected by:	Jason Young
Published by:	Glen Charlton
Inspection Date:	15 Apr 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			6.4 mm
Right front			6.0 mm
Left rear			5.0 mm
Right rear			6.0 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____