

Report ID:	24,876,874	Version:	1
Created:	28 Apr 2026		


Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2019
Rego No.:	MKB489	Rego Expiry:	19 Jun 2026
WoF Expiry:	25 Jul 2026	Odometer:	177,899 Kms
Good No.:	24876874	VIN:	MPBUMFF50KX240159
Next Service:	188,500kms	Service History:	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Paint is cracked and flaking on front bumper. Left door mirror repeater has small crack and water inside. Paint is flaking around dent on left cant rail. Left lock key cylinder of canopy back door has blockage. Right front door seal is worn, torn. 1 of roof rack end cap is missing.

Conditions During Body Inspection:  Wet     Dry

### Under Carriage and Under Bonnet Inspection Comments

### Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Rear door handles paint is worn.
Dashboard:	Good

### General Comments

Sunglasses holder is broken. One of remote key has flat battery.

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Yuki Itohara	
Published by:	Yuki Itohara	
Inspection Date:	28 Apr 2026	

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			4.5 mm
Right front			4.5 mm
Left rear			4.5 mm
Right rear			4.5 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys		2	
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_