

Report ID:	24,876,890	Version:	2
Created:	28 Apr 2026		


Make:	Holden	Model:	Commodore
Body Style:	Wagon	Year:	2020
Rego No.:	MTE601	Rego Expiry:	11 Mar 2027
WoF Expiry:	07 Apr 2027	Odometer:	188,411 Kms
Good No.:	24876890	VIN:	W0VZM8EC7L1009019
Next Service:	190,000km's	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Holes in all corners of front and rear bumpers. Rubber grommet/dome & four R/T aerial base fitted to roof panel. Chrome trim broken on right side of rear bumper. Small dent in right side sill & small dent in left side sill, under both front doors.

Conditions During Body Inspection

Dry

Under Carriage and Under Bonnet Inspection Comments

Oil leak from engine. Right side outer cv boot is starting to split.

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Average
Dashboard:	Average

General Comments

Screw holes in dashboard & left side of centre console. Hole in top of centre console. Bolt holes in left front foot well area. Drivers door frame seal is damaged & torn. Holes in interior panel on tailgate. Boot floor panel missing. Left front & right rear radio speakers are not working.

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Jason Young	
Published by:	Glen Charlton	
Inspection Date:	28 Apr 2026	

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			5.5 mm
Right front			5.5 mm
Left rear			5.5 mm
Right rear			5.5 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____