


Report ID:	24,877,207	Version:	2
Created:	12 May 2026		

Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2022
Rego No.:	PEU594	Rego Expiry:	27 Jul 2026
WoF Expiry:	05 Aug 2026	Odometer:	100,323 Kms
Good No.:	24877207	VIN:	MPBUMFF60NX387967
Next Service:	112,600kms	Service History:	Yes

**Note: This report is not a warranty**  
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**  
 S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Has a small stone crack in right side viewing area of windscreen. Right side corner of rear bumper has been pushed into rear guard, need realignment/refitted. Left and right front bumper mouldings cracked, Right side of nudge bar bent,

Conditions During Body Inspection:  Dry  Wet

### Under Carriage and Under Bonnet Inspection Comments

### Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

### General Comments

Has phone kit fitted on right side of dashboard & an aerial fitted o left front guard.

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No      Kms
Inspected by:	Jason Young
Published by:	Steve Ingram
Inspection Date:	07 May 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			8.0 mm
Right front			8.0 mm
Left rear			5.5 mm
Right rear			6.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_