

Report ID:	24,877,662	Version:	2
Created:	27 May 2026		


Make:	Mitsubishi	Model:	Triton
Body Style:	Utility	Year:	2021
Rego No.:	NHN227	Rego Expiry:	30 Nov 2026
WoF Expiry:	04 Mar 2027	Odometer:	220,775 Kms
Good No.:	24877662	VIN:	MMAJLKK10MH003338
Next Service:	no record	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Right door mirror cover has minor dent. Paint is cracked around dent in tailgate and around pin dent in right rear door. Edge of both tail lights are cracked. Minor stone cracks in windshield. Minor bents on left cant rail. Screw holes inside of right front guard.

Conditions During Body Inspection:  Wet     Dry

**Under Carriage and Under Bonnet Inspection Comments**

**Interior Comments**

Seats:	Right front base pad is worn, torn.
Carpets:	Right front foot rest area is torn.
Panels:	Right rear door trim is scuffed.
Dashboard:	Clips of Bluetooth microphone in roof are broken.

**General Comments**

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Yuki Itohara	
Published by:	Yuki Itohara	
Inspection Date:	27 May 2026	

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			9 mm
Right front			9 mm
Left rear			9 mm
Right rear			9 mm
Spare			
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_