

Report ID:	24,878,610	Version:	1
Created:	08 Jul 2026		


Make:	Suzuki	Model:	Grand Vitara
Body Style:	SUV	Year:	2012
Rego No.:	GND605	Rego Expiry:	11 Sep 2026
WoF Expiry:	10 Sep 2026	Odometer:	124,703 Kms
Good No.:	24878610	VIN:	JSAJTAA4V00250524
Next Service:	133,000km's	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Holes on inside lip of left front guard, from where an aerial bracket has been fitted. Rear window wiper blade needs replaced.

Conditions During Body Inspection:  Dry  Wet

### Under Carriage and Under Bonnet Inspection Comments

### Interior Comments

Seats:	Average
Carpets:	Good
Panels:	Average
Dashboard:	Good

### General Comments

Bolt holes in rear edge of interior roof lining, from where the cargo barrier has been fitted. Comes with cargo barrier. Stitching split on backrest of drivers seat. Radio clock is not working correctly.

Road Conditions During Test Drive	Wet	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Jason Young	
Published by:	Glen Charlton	
Inspection Date:	08 Jul 2026	

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			3.0 mm
Right front			3.8 mm
Left rear			2.0 mm
Right rear			3.2 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_