

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Both tail light is cracked (Corners only). Rear bumper reinforcement is bent. (Alignment required). Right sill paint is worn in front step area.

Under Carriage and Under Bonnet Inspection Comments

General Comments

I have read and understood
this condition guide:

NAME _____

SIGNATURE

Spare	Yes
-------	-----

Reversing camera	✓		
------------------	---	--	--