

## **Basic Condition Guide**

Report ID:	24,912,769	Version:	3
Created:	31 Oct 2025		

	Dillei		C Condition Guide	Created:	31 Oct 2025				
Mala	Mitaubiahi	Ma dali	Outlander				Requires		
Make:	Mitsubishi SUV	Model:	Outlander 2022			ОК	Attention	N/A	
Body Style:	PJL993	Year:		Engine					
Rego No.:	1. 2.222	Rego Expiry:	19 Jan 2026	Oil level		<b>'</b>			
WoF Expiry: 31 Oct 2026		Odometer:	57,951 Kms	Smoke & fumes		•			
Good No.:	24912769	VIN:	JMFXDGN0WNZ500267	Engine performance		1			
Next Service:	62754kms	Service History:	Yes	Noise		/			
Note: This report is This report is a guide	not a warranty e only. Consideration is made	de for age and mileage.	Coolant co	ondition	1				
diagnostic testing ur	ndertaken. The vehicle ha k ection prior to purchase an	been driven up to 50km/	Cooling pe	erformance	<b>/</b>				
Key			Radiator /	Hoses (visual)	<b>/</b>				
•	= Rust	Crack *= Deca	ls W = Significant scuffs	Transmission					
D = Dent P	T = Paint defect P = P	Pin dent SC = Sto	Operation		<b>'</b>				
		SP SP	S	Noise		<b>'</b>			
				Clutch				<b>/</b>	
			S	CV joints		<b>/</b>			
	TO ST			Wheel bea	arings	/			
SC				Brakes					
	MC 11			Performar	nce	1			
			P SC	Hand brak	ie	1			
S SC	18			Tyres (lowest observed tread depth of tyres)					
		Left front 3.3 mm							
					front 4.0 mm				
						2.7 mm			
		SP SD		Right rear		3.2 mm			
Note: some defects	and blemishes may not be	e displayed in the diagra	m	Spare	Spare No				
Body Inspecti	on Comments			Suspension	on				
Cargo Area Do	or Seal torn.			Suspensio	n performance	1			
Jack missing				Steering p	erformance	1			
				Shock abs	orbers	•			
Conditions Du	ring Body Inspection		Dry	Air Conditioning / Heater					
Under Carriag	e and Under Bonnet	t Inspection Comm	Operation		•				
				Electrical	/ Accessories				
				Head light	:S	V			
				Tail lights		~			
Interior Comn	nents			Indicators		1			
Seats:	Good			Dashboard warning lights		1			
Carpets:	Good			Wipers (front & rear)		1			
Panels:					vinder FL	•			
Dashboard: Good					vinder FR	1			
General Comr	ments		Window w	vinder RL	1				
				Window w	vinder RR	1			
				Rear view		1			
				Radio (bas	ic test only)	1			
Road Condition	ns During Test Drive		CD (basic t				<b>/</b>		
Road Conditions During Test Drive Dry Engine Timing Mechanism Timing Chain				Number of keys 2					
	m Belt Replacement	Yes	No Kms	Central loc	· ·	1			
Inspected by:	Lindsay Malpas			Remote lo		1			
,,,	1 2 2 3 1 1 2 3 2 3	231010	3	<u> </u>					

I have read and understood this condition guide:

Inspection Date: 29 Oct 2025

Malcolm Thomas

Published by:

NAME SIGNATURE

Sat. nav. (basic test only)

Reversing camera