


Make:	Holden	Model:	Captiva 5
Body Style:	SUV	Year:	2013
Rego No.:	GYT496	Rego Expiry:	07 Jan 2026
WoF Expiry:	20 Aug 2026	Odometer:	182,609 Kms
Good No.:	24912867	VIN:	KL3DD266JDB039954
Next Service:	Overdue.	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Space saver on but original tyre is in boot.
One reverse sensor is missing.
Front passenger interior door handle snapped off.

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

Oil leak.

Interior Comments

Seats:	Poor
Carpets:	Poor
Panels:	Average
Dashboard:	Average

General Comments

Scraping noise from front when exceeding 40 kms unable to diagnose.
Central and remote locking doesn't not lock rear left door and must be locked manually from door.
A/C doesn't push cold air.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Flynn Burdon
Published by:	Malcolm Thomas
Inspection Date:	30 Oct 2025

Report ID:	24,912,867	Version:	1
Created:	30 Oct 2025		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			3.8 mm
Right front			3.9 mm
Left rear			7.6 mm
Right rear			3.8 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation		✓	
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking		✓	
Remote locking		✓	
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide: _____

NAME

SIGNATURE