

# **Basic Condition Guide**

•	Report ID:	24,913,169	Version:	2
	Created:	26 Nov 2025		


	ОК	Requires Attention	N/A
Engine	<u> </u>	/ (ctcirtion	14/71
Oil level	V		
Smoke & fumes	1		
Engine performance	•		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	/		
Transmission			<u> </u>
Operation	·		
Noise	1		
Clutch			
CV joints	<b>V</b>		<del>ا</del>
Wheel bearings	<i>y</i>		
Brakes	_	L	
Performance	V		
Hand brake	<i>J</i>		
Tyres (lowest observed tread d	enth of	tvres)	
Left front	Сригог		1.0 mm
Right front			3.5 mm
Left rear			3.0 mm
Right rear			3.5 mm
Spare	Yes		
Suspension	100		
Suspension performance	<b>V</b>		
Steering performance	<i>y</i>		
Shock absorbers	<i>y</i>		
Air Conditioning / Heater			
Operation Operation	<b>V</b>	Ι	
Electrical / Accessories			
Head lights	<b>V</b>	1	
Tail lights	<i>'</i>		
Indicators	<i>y</i>		
Dashboard warning lights	<i>y</i>		
Wipers (front & rear)		<i>\</i>	
Window winder FL	<b>/</b>	-	
Window winder FR	<i>'</i>		
Window winder RL			
Window winder RR			
Rear view mirrors	J		<u> </u>
Radio (basic test only)	<i>J</i>		
CD (basic test only)			
Number of keys	2	l	
Central locking	<i>'</i>		
Remote locking	<i>'</i>		<u> </u>
Sat. nav. (basic test only)			
Reversing camera	<b>/</b>		<del>-</del>
neversing carriera		<u> </u>	

Make:	LDV	Model:	G10
Body Style:	Van	Year:	2021
Rego No.:	NUR746	Rego Expiry:	15 Nov 2025
WoF Expiry:	06 Nov 2025	Odometer:	38,588 Kms
Good No.:			LSKG4GL18MA123880
Next Service:			Yes
Note: This report is	•		
			arts have not been dismantled or h from cold. The Vendor recommend:

full mechanical inspection prior to purchase and this can be arranged for an additional charge.

# Key

W = Significant scuffs S = ScratchR = RustC = Crack\* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

## **Body Inspection Comments**

Front passenger tyre worn down to wire.

Minor stone chip in windscreen.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

#### **Interior Comments** Seats: Average Poor Carpets: Panels: Average Dashboard: Average

### **General Comments**

Jack tools missing.

Interior very poor obvious commercial use.

Rear door light fault, stays on and will flatten battery. Looks like wiring fault..

Rear wiper doesn't move.

Real wiper decent thieve.			
Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Flynn Burdon		
Published by:	Chris McQuade		
Inspection Date:	25 Nov 2025		

I have read and understood
this condition guide:

NAME			

SI	GN	AT	URF	