


Make:	Hyundai	Model:	I30
Body Style:	Wagon	Year:	2020
Rego No.:	NEZ135	Rego Expiry:	31 Dec 2025
WoF Expiry:	11 Dec 2025	Odometer:	126,122 Kms
Good No.:	24913225	VIN:	TMAH381AVLJ072637
Next Service:	139823 Kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Right sill damaged. Decal damage to rear bumper, spoiler, tailgate, right quarter panel. Only 1 Key Remote working. Front bumper cracked in both corners. Decal damaged paint on the back of vehicle. Scuff on right hand door.

Conditions During Body Inspection

Dry

## Under Carriage and Under Bonnet Inspection Comments

## Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

## General Comments

Front bumper and Bonnet damaged.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No    Kms
Inspected by:	Chris McQuade
Published by:	Nitiphum Yordsiri
Inspection Date:	02 Dec 2025

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

Report ID:	24,913,225	Version:	3
Created:	13 Dec 2025		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			3.2 mm
Right front			3.3 mm
Left rear			4.7 mm
Right rear			5.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

SIGNATURE \_\_\_\_\_