

•	Report ID:	24,913,391	Version:	1
	Created:	17 Dec 2025		

OK

Requires Attention

N/A

Basic Condition Guide					24,91
	umer	<u> </u>	Condition Guide	Created:	17 De
Make:	Isuzu	Model:	D-MAX		
	Utility	Year:	2017		
Body Style:	,			Engine	
Rego No.:	KJS249	Rego Expiry:	20 Dec 2026	Oil level	
WoF Expiry:	28 Jan 2026	Odometer:	226,352 Kms	Smoke & fu	ımes
Good No.:	24913391	VIN:	MPATFS85JGT007700	Engine per	forman
Next Service:	Overdue	Service History:	No	Noise	
Note: This report is not a warranty This report is a quide only. Consideration is made for age and mileage. Parts have not been dismantled or					ndition
	dertaken. The vehicle has b ection prior to purchase an		n from cold. The Vendor recommends a or an additional charge.	Cooling pe	rformar
Key				Radiator / H	loses (v
S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs					ion
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips					
S SC S P S D SC					
330		3 T	D 30	Clutch	
	(A)			CV joints	
				Wheel bear	rings
S SC				Brakes	
				Performan	ce
			SC	Hand brake	2

SP

D SC

Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Left Running Board Cracked.

Crack and Chips in Windscreen

Crack in Left Tail Light

Crack in right taillight

Crack in right tallight	
Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comments	

SP

Interior Comments	
Seats:	Poor
Carpets:	Average
Panels:	Average
Dashboard:	Average
General Comments	

4x4

Drivers Seat torn on Outside Edge

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Kees Gould	
Published by:	Kieran Driver	
Inspection Date:	15 Dec 2025	

I have read and understood			
this condition guide:	NAME		

Engine performance	/		
Noise	1		
Coolant condition	V		
Cooling performance	1		
Radiator / Hoses (visual)	/		
Transmission			
Operation	'		
Noise	1		
Clutch			/
CV joints	•		
Wheel bearings	•		
Brakes			
Performance	'		
Hand brake	1		
Tyres (lowest observed tread d	lepth of	tyres)	
Left front		6	6.7 mm
Right front		7	7.4 mm
Left rear		6	3.0 mm
Right rear		5	5.5 mm
Spare	Yes		
Suspension			
Suspension performance	'		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater	ı		
Operation	V		
Electrical / Accessories			
Head lights		V	
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	\(\tau \)		
Window winder FR	1		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			/
Number of keys	3		
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)			/
Reversing camera	1		
			·

IGNATURE		