

Report ID: 24,981,946 3 Version: 08 Apr 2025 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2019	Registration:	MCK647	Reg Expiry:	17 Apr 2025	Engine			
WoF Expiry:	17 Apr 2026	Odometer:	252,996 Kms	Good No:	24981946	Oil level	~		
VIN:	MPBUMFF50KX213972	Next Service:	28/11/25 or 255000km	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
					Drc	Performance	~		
Key:	SC	-0	S P SC P SC	-161-	D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	CSCW 6/6			The	SP SP	Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		•
* = decals SC Q Q						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SD SD SD P						Performance	~		
		Note: con	ne defects & blemishes			Hand Brake			
Body Insp	pection Comments	Note. son	le délects & blemisnes	indy not be disp	hayed in the diagram		 		
Dent LH rear door.						Tyres (lowest observed tread depth of tyres)			
Passenger side step bent up.						Left front	2.	-	mm
Dent in LH rear door sill. Missing front ford badge.						Right front			mm
						Left rear		3 mr	
Conditions During Body Inspection: Dry						Right rear 3 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & Under bor	met inspectio	on comments			Suspension			
Front bumper bottom skirt loose.						Suspension performance	~		
						Steering performance	~		
Surface corrosion around tow bar.						Shock absorbers	~		
						Air Conditioning / Heater			
	· · · · · · · · ·					Operation	~		
Interior Comments						Electrical / Accessories			
Seats	ok besides	s drivers seat ripp	oed.			Head lights	~		
Carpote						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Vehicle drove well.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		I
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
	•	-					-		
Inspected by: Jayden Roxburgh Date: 08 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: