

Report ID: 24,982,621 4 Version: 20 May 2025 Created:

Year:       2014       Registration:       HKM603       Reg Expiry:       30 Apr 2026         WoF Expiry:       30 May 2026       Odometer:       201,079 Kms       Good No:       24982621       Oil level       ✓         VIN:       5N1AR2MM7EC632465       Next Service:       20/05/26 or 211000kms       Service History:       No       Oil level       ✓         Mote: This report is not a warranty       This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.       Performance       ✓         Kerw       S       W       S       Performance       ✓	
VIN:       5N1AR2MM7EC632465       Next Service:       20/05/26 or 211000kms       Service History:       No         Note: This report is not a warranty       Smoke & fumes       ✓         This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.       Smoke & fumes       ✓         Service History:       No       Smoke & fumes       ✓         Performance       ✓           Performance       ✓           Performance       ✓           Performance       ✓           Performance       ✓           Performance       ✓           Performance       ✓           Performance       ✓           Second	
Note: This report is not a warranty       Performance       Image: Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.       Performance       Image: Performance         S       S       S       Mu       S       Performance       Image: Performance	
Note: This report is not a warranty         This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.         Noise	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.       Noise	
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Cooling System Coolant condition V Performance V	
a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Coolant condition	
Performance V	
Key:	
S = scratch	
D = dent	
R=rust	
PT = paint defect C = crack	~
P = pin dent	
*= decals SC PID	
SC = stone chips	
W = significant scuffs S W S SC S SC W S Performance	
Body Inspection Comments       Note: some defects & blemishes may not be displayed in the diagram       Hand Brake <ul> <li>Hand Brake</li> <li>Hand Brake</li> </ul>	
Missing drivers door bottom trim.	of tyres)
Left front 5	mm
Right front 5	mm
Left rear 5	mm
Conditions During Body Inspection:     Dry     Right rear     5	mm
	Yes
Under Carriage & Under Bonnet Inspection Comments Suspension	
Suspension performance 🗸	
Steering performance 🖌	
Shock absorbers 🖌	
Air Conditioning / Heater	
Operation 🗸	
Interior Comments Electrical / Accessories	I
Seats Good Head lights 🗸	
Tail lights 🗸	
Carpets Good Indicators 🖌	
Panels     Average     Dashboard warning lights     ✓	
Wipers (front & rear)	
Dashboard Good Window winder FL	
Window winder FR	
General Comments Window winder RL	
Vehicle drove well.	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)  V Number of keys 2	
Road Conditions During Test Drive:     Dry         Central locking	
Engine Timing Mechanism: Timing Chain	
Suidense of Cam Bolt Deplacement: Next A self-self self self self self self self self	~
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera 🖌	
Inspected by: Jayden Roxburgh Date: 20 May 2025	

I have read and understood this condition guide.

Name: .....

Signature: .....