

Report ID: 24,982,728 1 Version: 28 May 2025 Created:

Make:	Great Wall	Model:	V-Series	Body Style:	Utility		Pass	Fail	N/A
Year:	2014	Registration:	HHP888	Reg Expiry:	09 Jul 2025	Engine			
WoF Expiry:		Odometer:	272,895 Kms	Good No:	24982728	Oil level	~		1
VIN:	LGWCB3372DB676291	Next Service:	10/8/25 or 273000km	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	S PT	-0	ls			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	PT SC AL			The	BID				1
R = rust				10	JAIN	Operation	~		
PT = paint def C = crack	ect			+		Noise Clutch	~		
C = crack P = pin dent	LH						~		
* = decals	SSC QR					CV joints	~		
SC = stone chips						Wheel bearings			
W = significant scuffs S PT S P						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
Stone chips in windscreen.						Tyres (lowest observed tread depth of tyres)			
	drivers side b pillar.					Left front	5		mm
						Right front	5	5	mm
						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Surface cor	rosion underneath veh	icle.				Suspension performance	~		
Rust under	front bumper on brack	ets and supports.				Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Compete						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ird Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
Vehicle dro	ove ok.					Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		1
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		1
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 263,372						Reversing camera			~
						-	1		
Inspected by: Aaron Johnson Date: 28 May 2025									

I have read and understood this condition guide.

Name:

Signature: