

Basic Condition Guide

•	Report ID:	24,984,554	Version:	3
	Created:	13 Nov 2025		

	Ulliel	<u> </u>		Created:	13 Nov 2025				
Make:	: Volkswagen Model: Golf				Requires				
Body Style:	Wagon	Year:	2005		OK	Attention	N/A		
Rego No.:			20 Apr 2026	Engine			1		
WoF Expiry:	27 Nov 2026	Odometer:	118,746 Kms	Oil level	✓		<u> </u>		
Good No.:	24984554	VIN:	WVWZZZ1JZ6W006796	Smoke & fu	umes 🗸		ļ		
Next Service: 7/8/26 or 127000km		Service History:		Engine per					
		Service History.	Noise	✓		ļ			
Note: This report is This report is a guide	e only. Consideration is mad	de for age and mileage.	Coolant co	ondition					
diagnostic testing u full mechanical insp	ndertaken. The vehicle has l pection prior to purchase ar	been driven up to 50kn nd this can be arrange	Cooling pe	erformance 🗸					
Key			Radiator / I	Hoses (visual)					
•	C = Rust $C = C$	Crack *= De	cals W = Significant scuffs	Transmiss	ion				
D = Dent P	T = Paint defect P = F	Pin dent $SC = St$	Operation 🗸						
S		PSP	P	Noise	✓				
				Clutch			/		
	<u></u>		W	CV joints	✓				
	MA UT	+		Wheel bea	rings				
W				Brakes	Brakes				
				Performan	ce 🗸				
			R	Hand brak	e 🗸				
S D	18			Tyres (lowest observed tread depth of tyres)					
				Left front 4 mm					
			S	Right front	:		4 mn		
				Left rear	eft rear 4 mn				
)(P		Right rear			4 mn		
Note: some defects	and blemishes may not be	e displayed in the diag	gram	Spare	Ye	Yes			
Body Inspect	ion Comments			Suspensio	n				
Right rear door	doesn't shut fully, be	ent and dented aro	und latch.	Suspension	n performance				
				Steering p	erformance 🗸				
				Shock abso	orbers 🗸				
Conditions Du	ring Body Inspection		Dry	Air Condit	tioning / Heater				
Under Carria	ge and Under Bonne	t Inspection Com	Operation	✓					
All ok				Electrical	Electrical / Accessories				
				Head light	s 🗸				
				Tail lights	•				
Interior Comr	nents			Indicators	·				
Seats:	Good			Dashboard	d warning lights		<u> </u>		
Carpets:	Good	<u> </u>		Wipers (fro					
Panels:	average and roof	f liner sagging.		Window w					
Dashboard:	Good		Window w			1			
General Com	ments		Window w	rinder RL					
Vehicle drove v				Window w					
				Rear view i		+	 		
					ic test only)	+			
Road Conditio	ns During Test Drive	Dry	CD (basic t	,,	+				
Engine Timing Mechanism Cambelt				Number of	251 01)				
	am Belt Replacement	Yes	Central loc	. neys	Τ				
Inspected by:	-		No Kms	Remote lo		+	 		
inspected by.	Jayacii itoxbalgi	•		ricinote 10	2111119	1	1		

I have read and understood this condition guide:

Inspection Date: 13 Nov 2025

Published by:

NAME ____

Jayden Roxburgh

SIGNATURE

Sat. nav. (basic test only)

Reversing camera