

Report ID:	24,984,577	Version:	1
Created:	11 Nov 2025		


Make:	Suzuki	Model:	Grand Vitara
Body Style:	SUV	Year:	2005
Rego No.:	CUW873	Rego Expiry:	10 Aug 2026
WoF Expiry:	31 Oct 2026	Odometer:	151,113 Kms
Good No.:	24984577	VIN:	JSAFTD62V00250844
Next Service:	31/10/26 or 161105km	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Stone chips in windscreen.  
Left rear bumper trim loose.  
Paint flaking off majority of rear bumper.

Conditions During Body Inspection	Dry
-----------------------------------	-----

### Under Carriage and Under Bonnet Inspection Comments

Both front cv boots torn.  
Surface corrosion around tow bar.

### Interior Comments

Seats:	Good
Carpets:	Average
Panels:	Good
Dashboard:	Good

## General Comments

Vehicle drove well.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Aaron Johnson		
Published by:	Aaron Johnson		
Inspection Date:	11 Nov 2025		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front			6 mm
Right front			6 mm
Left rear			5 mm
Right rear			5 mm
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

**SIGNATURE**