

•	Report ID:	24,984,651	Version:	2
	Created:	03 Dec 2025		

Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2022
Rego No.:	PBD252	Rego Expiry:	09 Feb 2026
WoF Expiry:	05 Mar 2026	Odometer:	107,914 Kms
Good No.:	24984651	VIN:	MPBUMFF60MX376403
Next Service:	17/6/26 or 105000km	Service History:	Yes
diagnostic testing un	only. Consideration is made	een driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a for an additional charge.
Key			1
•	= Rust C = C	irack *= Deca	ls W = Significant scuffs
D = Dent P	Γ = Paint defect $P = P$	in dent SC = Sto	ne Chips
S SC		S P SC	W
$\overline{}$	$\overline{}$	\top	
			(0)
		1	
$\neg \neg \rho$	18		
1		$\mathbb{N} \cup \mathbb{N}$	S
s sc			
			SPW
SC			
	and blemishes may not be	displayed in the diagra	am
body inspecti	on Comments		
Tail gate loose	and not attached right	t hand side missing	j bolt.
ran gate 100se	er front bumper grille.		
J			
Damage to lowe	ing Rody Inspection		Dry
Damage to lower	ring Body Inspection	Inspection Comm	Dry
Conditions Dur	e and Under Bonnet		· '
Damage to lower Conditions Dur			· '
Damage to lower Conditions Dur	e and Under Bonnet		· '
Conditions Dur Under Carriag Surface corrosio	e and Under Bonnet on underneath vehicle		· '
Conditions Dur Under Carriag Surface corrosio	e and Under Bonnet on underneath vehicle		· '
Conditions Dur Under Carriag Surface corrosic Interior Comm	e and Under Bonnet on underneath vehicle nents Good		· '
Conditions Dur Under Carriag Surface corrosic Interior Comm Seats: Carpets:	ne and Under Bonnet on underneath vehicle ments Good Good		· '
Conditions Dur Under Carriag Surface corrosic Interior Comm	e and Under Bonnet on underneath vehicle nents Good		· '

	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	1		
Engine performance	1		
Noise	•		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission		1	
Operation	/		
Noise	1		
Clutch			/
CV joints	_		
Wheel bearings	/		
Brakes		l	
Performance	/		
Hand brake	<i>y</i>		
Tyres (lowest observed tread d	enth of	tyres)	
Left front	Сригог	tyrcs)	7 mm
Right front			7 mm
Left rear			
Right rear	Vas		/ mm
Spare	Yes		
Suspension		Ι	
Suspension performance	-		
Steering performance	•		
Shock absorbers	•		
Air Conditioning / Heater		I	Г
Operation	/		
Electrical / Accessories		ı	
Head lights	/		
Tail lights	•		
Indicators	•		
Dashboard warning lights	•		
Wipers (front & rear)	•		
Window winder FL	V		
Window winder FR	~		
Window winder RL	•		
Window winder RR	•		
Rear view mirrors	'		
Radio (basic test only)	•		
CD (basic test only)			V
Number of keys	1		
Central locking	'		
Remote locking	1		
Sat. nav. (basic test only)	1		
Reversing camera	1		
-			

Road Condition	s During Test Drive	Dry		
Engine Timing N	Mechanism	Cambelt		
Evidence of Cam Belt Replacement		Yes	V No	Kms
Inspected by:	Jayden Roxburgh			
Published by:	Jayden Roxburgh			
Inspection Date:	03 Dec 2025			

I have read and understood
this condition guide:

Vehicle drove well. Service due.

NAME			