

Basic Condition Guide

•	Report ID:	24,984,667	Version:	2
	Created:	03 Dec 2025		


	ОК	Requires Attention	N/A
Engine	Jit	710011	14//1
Oil level	V		
Smoke & fumes	1		
Engine performance	1		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission		1	
Operation	V		
Noise	1		
Clutch			1
CV joints	1		
Wheel bearings	1		
Brakes	-		
Performance	V		
Hand brake	1		
Tyres (lowest observed tread of	depth of	tyres)	
Left front	İ		1 mn
Right front			1 mn
Left rear			1 mn
Right rear			1 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater		1	
Operation	V		
Electrical / Accessories			
Head lights	V		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	1		
Window winder RL	1		
Window winder RR	•		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)	1		
Number of keys	2		
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)	1	1	
Reversing camera	1		

Ford	Model:	Ranger
Utility	Year:	2020
NEB155	Rego Expiry:	29 May 2026
15 Jan 2026	Odometer:	146,715 Kms
24984667	VIN:	MPBUMFF60LX307852
25/8/26 or 158000km	Service History:	Yes
not a warranty		
	Utility NEB155 15 Jan 2026 24984667 25/8/26 or 158000km	Utility Year: NEB155 Rego Expiry: 15 Jan 2026 Odometer: 24984667 VIN: 25/8/26 or 158000km Service History:

full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

itcy				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Right front fog light lens broken.

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

All 4 tyres need replacing, tyres all under 1mm on inner and outer edge.

Interior Comm	nents	
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comments		

Vehicle drove well.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	V No	Kms
Inspected by:	Jayden Roxburgh			
Published by:	Jayden Roxburgh			
Inspection Date:	03 Dec 2025			

ıŀ	nave	read	and	unde	ersto	od
tŀ	nis co	nditi	on a	uide	:	

NAME		