

•	Report ID:	24,985,131	Version:	1
	Created:	02 Dec 2025		

Basic Condition Guide			Report ID:	24,985,131	Ve	rsion: 1		
	oniei			Created:	02 Dec 2025			
Make:	Holden	lden Model: Commodore				OV	Requires	
Body Style:	Utility	Year:	2017	Engine		OK	Attention	N/A
Rego No.:	LBG481	Rego Expiry:	30 Nov 2026	Oil level		V	İ	
WoF Expiry:	04 Nov 2026	Odometer:	234,632 Kms	Smoke & fu	ımer	1		
Good No.:	24985131	VIN:	6G1FA4E30HL315128	Engine per		1		
Next Service:	5/6/26 or 245000km	Service History:	No	Noise	TOTTIATICE	1		
Note: This report is	not a warranty	•	,	Coolant co	ndition	1		
diagnostic testing un	dertaken. The vehicle has b	een driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a	Cooling pe		1		_
full mechanical inspe	ection prior to purchase and	d this can be arranged f	or an additional charge.	- 31	Hoses (visual)	1		\vdash
Key	D	l * D	In the Constitution of the	Transmissi				
	= Rust $C = C$ = Paint defect $P = Pi$		ls W = Significant scuffs ne Chips	Operation		V		
	- runt defect 1 - 11		The Crips	Noise		1		\vdash
SD			SD	Clutch				\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
				CV joints		1		
			C	Wheel bear	rings	1		\vdash
DCW				Brakes				
					ce	V		
			sc	Hand brake	e	1		
S SC	R			Tyres (lowest observed tread depth of tyres)				
SD W D				Left front				6 mm
				Right front				6 mm
				Left rear				5 mm
				Right rear				5 mm
Note: some defects and blemishes may not be displayed in the diagram				Spare		Yes		
Body Inspection	on Comments			Suspensio	n			
Scratches in rigi	ht top corner of winds	creen.		Suspension	n performance	/		
				Steering pe	erformance	/		
				Shock abso	orbers	/		
Conditions During Body Inspection Wet				Air Condit	ioning / Heater			
Under Carriage and Under Bonnet Inspection Comments				Operation		/		
					Electrical / Accessories			
				Head lights	5	/		
				Tail lights		/		
Interior Comments			Indicators		/			
Seats: Good			Dashboard	l warning lights	/			
Carpets: Average			Wipers (fro	nt & rear)	/			
Panels: Good			Window w	inder FL	/			
Dashboard: good besides missing middle panel.			Window w	inder FR	~			
General Comm	General Comments			Window w	inder RL			/

	interior Comments			
	Seats:	Good		
	Carpets:	Average		
	Panels:	Good		
Dashboard: good besides missing middle panel.				
	Conoral Comments			

Vehicle drove well.

Road Conditions During Test Drive		Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Aaron Johnson	
Published by:	Aaron Johnson	
Inspection Date:	02 Dec 2025	

have read and understood						
this condition quide						

NAME			

SIGNATURE			

•

1

1

•

Window winder RR Rear view mirrors

Radio (basic test only) CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking