

# **Basic Condition Guide**

Report ID: 24,985,149		Version:	2
Created:	02 Dec 2025		

	OV	Requires	NI/A
Engine	OK	Attention	N/A
Oil level	V		1
Smoke & fumes	<i>y</i>		
Engine performance	1		
Noise Value of the last of the	V V		
Coolant condition	~		
Cooling performance	~		
Radiator / Hoses (visual)	V		
Transmission		<u> </u>	
	- J	1	1
Operation	1		
Noise			
Clutch			
CV joints	.,		
Wheel bearings			
Performance	.,	I	
	-		
Hand brake	, , , , , ,		
Tyres (lowest observed tread o	lepth of	tyres)	
Left front			4 mm
Right front			4 mm
Left rear			4 mm
Right rear			4 mm
Spare	Yes		
Suspension	1 .	ı	
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater	1 .		П
Operation	/		<u> </u>
Electrical / Accessories	1 .	ı	
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	V V		
Window winder FL			
Window winder FR	V		
Window winder RL			
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	2	,	
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			_
Reversing camera	<b>/</b>		


Make:	Skoda	Model:	Superb
Body Style:	Wagon	Year:	2022
Rego No.:	PKP422	Rego Expiry:	03 Aug 2026
WoF Expiry:	21 Aug 2026	Odometer:	205,559 Kms
Good No.:	24985149	VIN:	TMBKD9NP7N7041618
Next Service:	17/6/26 or 207000km	Service History:	No

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

# Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Part of bottom front bumper missing on RH side.

Holes in rear bumper.

Both front wheels and RH rear wheel missing centre caps.

Stone chips in windscreen.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

# Interior Comments Seats: ok besides drivers seat ripped. Carpets: Average Panels: Average Dashboard: average, holes and missing panel.

# **General Comments**

Vehicle drove well.

Fraying on front passengers seat belt.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Aaron Johnson	
Published by:	Aaron Johnson	
Inspection Date:	02 Dec 2025	

have read and understood
his condition quide

NAME			

SI	GN	IA.	ΓU	RF