

Report ID:	24,985,675	Version:	3
Created:	16 Dec 2025		

Лake:	Mazda	Model:	Bt-50
ody Style:	Utility	Year:	2021
Rego No.:	NYL477	Rego Expiry:	19 Feb 2026
WoF Expiry:	11 Feb 2026	Odometer:	106,040 Kms
Good No.:	24985675	VIN:	MP2TFS40JNT016221
Next Service:	9/10/26 or 114800km	Service History:	Yes
iagnostic testing u Ill mechanical insp	e only. Consideration is made	een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a or an additional charge. -
<b>(ey</b> 5 = Scratch F	t = Rust C = C	rack *= Deca	ls W = Significant scuffs
		in dent SC = Sto	
S D		SP SP	$\mathbb{V}$
-			
			S
s (			DAN /
	18		
0.00			
s sc			
			S
		SP SP	S
lote: some defects	s and blemishes may not be	displayed in the diagra	am .
	ion Comments	uispiayeu iii tile diagra	3111
Right taillight le			
Stone chips in	windscreen.		
Conditions Du	ring Body Inspection		Dry
	ge and Under Bonnet	Inspection Comm	nents
	eveloping underneath v		
-	not roadworthy, down	to wear indicators.	
Front rotors wo	ini anu iusiy.		
Interior Com	ments		
Seats:	Good		

		Requires	
	OK	Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	<b>V</b>		
Engine performance	•		
Noise	V		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission	<u> </u>	1	
Operation	~		
Noise	~		
Clutch			<b>/</b>
CV joints	~		
Wheel bearings	<b>'</b>		
Brakes			
Performance	~		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			4 mm
Right front			4 mm
Left rear			5 mm
Right rear		(	).6 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	1		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	1		
Tail lights	1		
Indicators	1		
Dashboard warning lights	~		
Wipers (front & rear)	/		
Window winder FL	1		
Window winder FR	1		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			V
Number of keys	2	I	<u> </u>
Central locking	_		
Remote locking	·		
Sat. nav. (basic test only)			
Reversing camera	<i>-</i>		
neversing Carriera		<u> </u>	

Interior Comm	ents
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good
General Comm	nents

Vehicle drove well.

Road Conditions During Test Drive		Dry
		Timing Chain
Engine Timing Mechanism		Tilling Chair
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Aaron Johnson	
Published by:	Aaron Johnson	
Inspection Date:	16 Dec 2025	

I have read and understood	k
this condition quide	

NAME			