

Report ID: 25,002,685 4 Version: 03 Apr 2025 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A
Year:	2021	Registration:	NSC927	Reg Expiry:	05 Aug 2025	Engine	1	1	
WoF Expiry:	06 Sep 2025	Odometer:	70,449 Kms	Good No:	25002685	Oil level	~		
VIN:	JMFXLGF6WLZ001504	Next Service:	79,000kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged fo	or an additional o	narge.	Coolant condition	~		
						Performance	~		
Key: S = scratch		=		5(0)-		Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	S SC			10		Operation	~		
PT = paint def	ect NP	1				Noise	~		
C = crack						Clutch			~
P = pin dent	SRSC DI				74HL	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
5		\sim				Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Stone chips in front screen						Left front	3	.0	mm
						Right front	4	.0	mm
						Left rear	2	.0	mm
Conditions During Body Inspection: Dry						Right rear	3.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Under Ca	rriage & Under Bor	inet inspectio	on Comments			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories	1		1
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		-
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	v		
General (Comments					Window winder FR Window winder RL	v		
						Window winder RL Window winder RR	~ ~		
Air conditioning and heating systems working, along with reverse camera at inspection time. Front washer aim poor						Rear view mirrors	<i>v</i> <i>v</i>		
						Radio (basic test only)	<i>v</i> <i>v</i>		
						CD (basic test only)			
						Number of keys	2		~
Pood Conditions During Test Driver						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
Evidence	of Cam Belt Replac		lot Applicable	Kms:		Reversing camera	~		+
									<u> </u>
Inspecte	d by: Gary Adams					Date: 19 Mar 20	25		

I have read and understood this condition guide.

Name: