

Basic Condition Guide

•	Report ID:	25,004,092	Version:	3
	Created:	03 Dec 2025		


Make:	Toyota	Model:	Hilux
Body Style:	Utility	Year:	2009
Rego No.:	EYF167	Rego Expiry:	29 Apr 2026
WoF Expiry:	02 Apr 2026	Odometer:	154,364 Kms
Good No.:	25004092	VIN:	MR0DZ22G500013406
Next Service:	163,000 Kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = ScratchR = RustC = Crack* = DecalsW = Significant scuffs D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

No keys for toolbox.

Headlights faded.

Paint faded and clear coat coming off n spots.

Several interior panels missing/damaged

Under Carriage and Under Report Inspection Comme	onte
Conditions During Body Inspection	Dry

Interior Comments		
Seats:	heavy fitted covers	
Carpets:	Average	
Panels:	scratches scuffs marks	
Dashboard:	holes previous fitted equipment	

General Comments

Air conditioning and heating systems along with reverse camera working at time of inspection.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	V No	Kms
Inspected by:	Gary Adams			
Published by:	Amanda Loader			
Inspection Date:	13 Nov 2025			

nave read and understood			
nis condition quide:	NAME		

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	✓		
Engine performance	/		
Noise	V V		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	V		
Clutch	~		
CV joints			1
Wheel bearings	/		
Brakes			
Performance	~		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front	•		5.0 mm
Right front			1.0 mm
Left rear			3.0 mm
Right rear			2.0 mm
Spare	Yes		
Suspension			
Suspension performance			
Steering performance	· /		
Shock absorbers			
Air Conditioning / Heater			
Operation			
Electrical / Accessories			
Head lights			
Tail lights	· /		
Indicators			
Dashboard warning lights			
Wipers (front & rear)			
Window winder FL	\(\tau \)		
Window winder FR	· /		
Window winder RL			·
Window winder RR			1
Rear view mirrors	/		
Radio (basic test only)	· ·		
CD (basic test only)			
Number of keys	1	<u> </u>	L
Central locking	· /		
Remote locking			
Sat. nav. (basic test only)	•		
Reversing camera			<u> </u>
neversing carriera			

SIGNATURE			