


# **Basic Condition Guide**

Report ID: 25,004,118		Version:	3
Created:	17 Dec 2025		

Make:	Subaru	Model:	Impreza		
Body Style:	Hatchback	Year:	2012		
Rego No.:	QKM171	Rego Expiry:	14 Feb 2026		
WoF Expiry:	18 Mar 2026	Odometer:	151,185 Kms		
Good No.:	25004118	VIN:	7AT0GF09X23008840		
Next Service:	154,000 Kms	Service History:	Yes		
Note: This report is not a warranty					

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

ĸey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

## **Body Inspection Comments**

Tire inflation device in the boot.

Headlights faded

Parcel tray missing

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Rear brake pads 3mm.

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

### **General Comments**

Air conditioning and heating systems along with re camera working at time of inspection. Lh mirror doesn't retract.

Handbrake travel excessive

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Amanda Loader	
Inspection Date:	12 Nov 2025	

I have read and understood						
this condition quide						

NAME			

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Cooling performance	<b>✓</b>		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			<b>'</b>
CV joints	<b>✓</b>		
Wheel bearings	/		
Brakes			
Performance		<b>/</b>	
Hand brake		<b>V</b>	
Tyres (lowest observed tread d	epth of	tyres)	
Left front		5	5.0 mm
Right front		6	6.0 mm
Left rear		Ę	5.0 mm
Right rear		(	6.0 mm
Spare	N/A		
Suspension			
Suspension performance	/		
Steering performance	<i>V</i>		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	✓ ✓		
Indicators	/		
Dashboard warning lights	V		
Wipers (front & rear)	/		
Window winder FL	V V		
Window winder FR	/		
Window winder RL	/		
Window winder RR			
Rear view mirrors	-		
Radio (basic test only)	/	-	
CD (basic test only)	· /		
Number of keys	1	L	
Central locking	· /		
Remote locking	· /		
Sat. nav. (basic test only)	•		
Reversing camera			<b>-</b>
	•	1	<u> </u>

SIGNATURE		