

Basic Condition Guide

•	Report ID:	25,004,141	Version:	1
	Created:	18 Nov 2025		

N/A

4.0 mm 4.0 mm 5.0 mm 6.0 mm

	ntue	S Bas	ic Condition Guide	Created: 18 Nov 2025		
Make:	Hyundai	Model:	Kona		ОК	Requires Attention
Body Style:	SUV	Year:	2022	Engine		
Rego No.:	PNR901	Rego Expiry:	19 Jan 2026	Oil level		
WoF Expiry:	20 Oct 2026	Odometer:	25,508 Kms	Smoke & fumes	V	
Good No.:	25004141	VIN:	KMHK281GUNU164493	Engine performance	V	
Next Service:	26,000 Kms	Service History:	Yes	Noise	V	
Note: This report is	•	ndo for ago and mileago. P	Coolant condition	1		
diagnostic testing ι	ındertaken. The vehicle has pection prior to purchase a	s been driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a for an additional charge	Cooling performance	1	
	pection prior to parchase a		or arradutional charge.	Radiator / Hoses (visual)	1	İ
Key S = Scratch 1	R = Rust C =	: Crack *= Deca	als W = Significant scuffs	Transmission		
	PT = Paint defect P =		ne Chips	Operation	V	
				Noise	V	
S SC		S		Clutch		
			S SC	CV joints	V	
	Ma Off		330	Wheel bearings	V	
S SC				Brakes		
	1191			Performance	V	
			Hand brake	V		
S SC	HR			Tyres (lowest observed tread	depth of	tyres)
				Left front		4
SSC				Right front		4
				Left rear	Left rear	
S SC		s <u>s</u>	S	Right rear		
Note: some defect	s and blemishes may not l	be displayed in the diagr	am	Spare	N/A	
	tion Comments	, , ,		Suspension		
Tire inflation d	evice is in the boot			Suspension performance	V	
				Steering performance		
				Shock absorbers	V	1
Conditions Du	uring Body Inspection	1	Dry	Air Conditioning / Heater		
Under Carria	ge and Under Bonne	et Inspection Comn	nents	Operation	V	
				Electrical / Accessories		
				Head lights	V	
				Tail lights	1	
Interior Comments				Indicators	V	
Seats:	Average			Dashboard warning lights	1	
Carpets: Average			Wipers (front & rear)	1		
Panels: Average			Window winder FL	1		
Dashboard: Average			Window winder FR	1		
General Com	_		Window winder RL	1		
Air conditioning	g and heating system	s along with reverse	Window winder RR	1		
inspection	side interior trim lease	Rear view mirrors	1			

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Unknown		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Gary Adams			
Published by: Amanda Loader				
Inspection Date:	18 Nov 2025			

have read and understood
his condition quide

A pillar driver side interior trim loose/broken

NAME			

SIGNATURE		

1

2

1

1

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only)

Reversing camera