


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Mitsubishi  | Model:           | Triton            |
| Body Style:   | Utility     | Year:            | 2023              |
| Rego No.:     | PYZ669      | Rego Expiry:     | 18 May 2026       |
| WoF Expiry:   | 16 May 2026 | Odometer:        | 71,718 Kms        |
| Good No.:     | 25004194    | VIN:             | MMAJLKL10PH013734 |
| Next Service: | 75,000 kms  | Service History: | Yes               |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Conditions During Body Inspection

Wet

## Under Carriage and Under Bonnet Inspection Comments

## Interior Comments

|            |         |
|------------|---------|
| Seats:     | Average |
| Carpets:   | Average |
| Panels:    | Average |
| Dashboard: | Average |

## General Comments

Air conditioning and heating systems along with reverse camera working at time of inspection.

|                                   |  |
|-----------------------------------|--|
| Road Conditions During Test Drive | Wet  |
| Engine Timing Mechanism           | Timing Chain   |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes <input type="checkbox"/> No Kms |
| Inspected by:                     | Gary Adams   |
| Published by:                     | Amanda Loader  |
| Inspection Date:                  | 19 Nov 2025  |

I have read and understood this condition guide:

NAME \_\_\_\_\_

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 25,004,194  | Version: | 2 |
| Created:   | 01 Dec 2025 |          |   |

|   | OK | Requires Attention | N/A     |
|---|----|--------------------|---------|
| <b>Engine</b>                                       |    |                    |         |
| Oil level   | ✓  |                    |         |
| Smoke & fumes                                       | ✓  |                    |         |
| Engine performance                                  | ✓  |                    |         |
| Noise   | ✓  |                    |         |
| Coolant condition                                   | ✓  |                    |         |
| Cooling performance                                 | ✓  |                    |         |
| Radiator / Hoses (visual)                           | ✓  |                    |         |
| <b>Transmission</b>                                 |    |                    |         |
| Operation   | ✓  |                    |         |
| Noise   | ✓  |                    |         |
| Clutch  |    |                    | ✓       |
| CV joints   |    |                    | ✓       |
| Wheel bearings                                      | ✓  |                    |         |
| <b>Brakes</b>                                       |    |                    |         |
| Performance   | ✓  |                    |         |
| Hand brake  | ✓  |                    |         |
| <b>Tyres (lowest observed tread depth of tyres)</b> |    |                    |         |
| Left front  |    |                    | 10.0 mm |
| Right front   |    |                    | 10.0 mm |
| Left rear   |    |                    | 10.0 mm |
| Right rear  |    |                    | 10.0 mm |
| Spare   |    | Yes                |         |
| <b>Suspension</b>                                   |    |                    |         |
| Suspension performance                              | ✓  |                    |         |
| Steering performance                                | ✓  |                    |         |
| Shock absorbers                                     | ✓  |                    |         |
| <b>Air Conditioning / Heater</b>                    |    |                    |         |
| Operation   | ✓  |                    |         |
| <b>Electrical / Accessories</b>                     |    |                    |         |
| Head lights   | ✓  |                    |         |
| Tail lights   | ✓  |                    |         |
| Indicators  | ✓  |                    |         |
| Dashboard warning lights                            | ✓  |                    |         |
| Wipers (front & rear)                               | ✓  |                    |         |
| Window winder FL                                    | ✓  |                    |         |
| Window winder FR                                    | ✓  |                    |         |
| Window winder RL                                    | ✓  |                    |         |
| Window winder RR                                    | ✓  |                    |         |
| Rear view mirrors                                   | ✓  |                    |         |
| Radio (basic test only)                             | ✓  |                    |         |
| CD (basic test only)                                |    |                    | ✓       |
| Number of keys                                      | 1  |                    |         |
| Central locking                                     | ✓  |                    |         |
| Remote locking                                      | ✓  |                    |         |
| Sat. nav. (basic test only)                         |    |                    | ✓       |
| Reversing camera                                    | ✓  |                    |         |

SIGNATURE \_\_\_\_\_