

•	Report ID:	25,004,248	Version:	3
	Created:	28 Nov 2025		


	OK	Requires Attention	
Engine	- OK	Attention	IN/A
Oil level	V		
Smoke & fumes	1		
Engine performance	V		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation			<u> </u>
Noise	1		
Clutch	+		1
CV joints	1		
<u> </u>	1		
Wheel bearings  Brakes			
Performance	.,,	l	
Hand brake	<b>V</b>		
Tyres (lowest observed tread	depth of		- 0
Left front			5.0 mm
Right front			5.0 mm
Left rear			5.0 mm
Right rear			5.0 mm
Spare	Yes		
Suspension		1	
Suspension performance	/		
Steering performance	/		
Shock absorbers	<b>/</b>		
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	V		
Tail lights	~		
Indicators	V		
Dashboard warning lights	~		
Wipers (front & rear)	1		
Window winder FL	/		
Window winder FR	/		
Window winder RL	V		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)	1		
Number of keys	1	<u> </u>	
Central locking	1	1	
	1		
Remote locking	1		
Sat. nav. (basic test only)	.,		
Reversing camera		<u> </u>	

Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2019
Rego No.:	MCK602	Rego Expiry:	16 Jan 2026
WoF Expiry:	04 Apr 2026	Odometer:	130,078 Kms
Good No.:	25004248	VIN:	MPBUMFF50KX213107
Next Service:	135,000 Kms	Service History:	Yes

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

itey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

# **Body Inspection Comments**

Conditions During Body Inspection Dry	

Battery was flat, recharged tested and passed

Interior Comments		
Seats:	marks	
Carpets:	Average	
Panels:	scratches scuffs marks	
Dashboard:	Average	

## **General Comments**

Air conditioning and heating systems along with reverse camera and navigation working at time of inspection.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Amanda Loader	
Inspection Date:	21 Nov 2025	

I have read and understood
this condition guide:

NAME			