

Basic Condition Guide


•	Report ID:	25,004,276	Version:	1
	Created:	18 Nov 2025		

		ОК	Requires Attention	N/A		
	Engine					
	Oil level	/				
	Smoke & fumes	/				
3219	Engine performance	/				
	Noise	/				
ed or	Coolant condition	/				
ommends a	Cooling performance	V				
	Radiator / Hoses (visual)	/				
cant scuffs	Transmission					
	Operation	V				
	Noise	/				
	Clutch			~		
S D SC	CV joints			~		
3030	Wheel bearings	/				
	Brakes					
*	Performance	V				
	Hand brake	1				
	Tyres (lowest observed tread	depth of	tyres)			
	Left front			1.0 mm		
	Right front			1.0 mm		
	Left rear		7	7.0 mm		
SD	Right rear		7.0 mm			
	Spare	Yes				
	Suspension					
	Suspension performance	V				
	Steering performance	1				
	Shock absorbers	1				
	Air Conditioning / Heater					
	Operation	V	Ι			
	Electrical / Accessories		l			
	Head lights	V				
	Tail lights	1				
	Indicators	1				
	Dashboard warning lights	1				
	Wipers (front & rear)	1				
	Window winder FL	V				
	Window winder FR	V				
	Window winder RL	1	 			
	Window winder RR	V	 			
	Rear view mirrors	1				
	Radio (basic test only)	1				
				J		
	CD (basic test only)	1	<u>I</u>			
	Number of keys	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	1			
Kms	Central locking	1	-			
	Remote locking	-				
	Sat. nav. (basic test only)			V		
	Reversing camera			<i>'</i>		

Dasic Condition Guide					
Make:	Holden	Model:	Commodore		
Body Style:	Sedan	Year:	2017		
Rego No.:	PHA945	Rego Expiry:	01 Dec 2025		
WoF Expiry:	19 Jul 2025	Odometer:	175,644 Kms		
Good No.:	25004276	VIN:	6G1FA5E58HL318219		
Next Service:	181,000 Kms	Service History:	Yes		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					
Key			W 6: :6		

v	_		
n	Ľ	٠,	,

W = Signific D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Front tires balding inner edges.

Front bumper poor fit.

Rear spoiler coming off

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Interior Comments			
Seats:	s: marks		
Carpets:	Average		
Panels:	scratches scuffs marks		
Dashboard:	Average		

General Comments

Air conditioning and heating systems working at time of inspection.

Park assist requires attention, non functional

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Amanda Loader	
Inspection Date:	18 Nov 2025	

I have read and	understood
this condition a	uide.

NAME			