

Report ID: 25,004,3		25,004,333	Version:	1
	Created:	18 Nov 2025		

		OK	Requires Attention	N/A	
	Engine				
	Oil level	V			
	Smoke & fumes	1			
3925	Engine performance	1			
	Noise				
	Coolant condition	1			
d or mmends a	Cooling performance	1			
	Radiator / Hoses (visual)	1			
	Transmission				
ant scuffs	Operation	V			
	Noise	1			
DRW	Clutch			_	
	CV joints	1			
S	•	1			
	Wheel bearings				
	Brakes		<u> </u>		
sc	Performance				
	Hand brake	<i>'</i>			
	Tyres (lowest observed tread	depth of			
sc	Left front			7.0 mr	
	Right front		8	3.0 mr	
	Left rear	4.0 mr			
S	Right rear	5.0 mr			
	Spare	Yes			
	Suspension				
	Suspension performance	/			
	Steering performance		/		
	Shock absorbers	V			
	Air Conditioning / Heater				
	Operation	V			
	Electrical / Accessories				
	Head lights	V			
	Tail lights	1			
	Indicators	V			
	Dashboard warning lights	1			
	Wipers (front & rear)	1			
	Window winder FL	1			
	Window winder FR	1			
	Window winder RL	1			
mera	Window winder RR	1			
	Rear view mirrors	V			
		· .			
	Radio (basic test only)	-			
	CD (basic test only)	2			
	Number of keys	2			
Kms	Central locking	/			
				i	

_			
OT	nue	S Basi	ic Condition Guide
Make:	Honda	Model:	Grace
Body Style:	Sedan	Year:	2015
Rego No.:	QGJ275	Rego Expiry:	14 May 2026
WoF Expiry:	14 Nov 2025	Odometer:	112,760 Kms
Good No.:	25004333	VIN:	7AT08GEDX23008925
Next Service:	107,500 Kms	Service History:	Yes
diagnostic testing un	only. Consideration is made	een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a or an additional charge.
	= Rust C = C = Paint defect P = Pi		ls W = Significant scuffs ne Chips
DW	SI	D*W SD*	SDRW
S SC W			A BID

D W	SD*W SD*	SDRW
		S
S SC W		
Alb		
		SC
SC W		
		SC
(sc)()	(SW)(S)	()(S

Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Headlights faded.

Factory tyre inflation kit provided.

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

General Comments

Air conditioning and heating systems good temperature along with reversing c working at inspection.

Requires wheel alignment, pulling right.

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Timing Chain		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Finlay Lemmens			
Published by:	Amanda Loader			
Inspection Date:	18 Nov 2025			

۱h	ave	read	and	under	stood
thi	is co	onditi	on a	uide:	

NAME		

:	IG	N	Δ.	ΓU	R	F	

Remote locking

Sat. nav. (basic test only) Reversing camera

•