

Basic Condition Guide

| • | Report ID: | 25,004,419 | Version: | 2 |
|---|------------|-------------|----------|---|
| | Created: | 19 Dec 2025 | | |

Engine Oil level

Noise

Smoke & fumes
Engine performance

Coolant condition

ОК

1

Requires

Attention

N/A


| Make: | Holden | Model: | Commodore |
|---------------|-------------|------------------|-------------------|
| Body Style: | Wagon | Year: | 2018 |
| Rego No.: | LKZ49 | Rego Expiry: | 06 Jun 2026 |
| WoF Expiry: | 24 May 2026 | Odometer: | 193,872 Kms |
| Good No.: | 25004419 | VIN: | W0VZM8EC7J1101664 |
| Next Service: | 197,000 Kms | Service History: | Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

| itcy | | | | |
|-------------|-------------------|--------------|------------------|------------------------|
| S = Scratch | R = Rust | C = Crack | * = Decals | W = Significant scuffs |
| D = Dent | PT = Paint defect | P = Pin dent | SC = Stone Chips | |



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Parcel tray and boot trim missing. Several holes, wires from police equipment.

| Conditions During Body Inspection | Dry | |
|---|-----|--|
| Under Carriage and Under Bonnet Inspection Comments | | |

Sump, exhaust pipe large dents

| Interior Comments | | | |
|--------------------|------------------------|--|--|
| Seats: | marks, hole | | |
| Carpets: | hole driver footwell | | |
| Panels: | scratches scuffs marks | | |
| Dashboard: Average | | | |

General Comments

Air conditioning and heating systems along with reverse camera working at time of inspection.

| Road Conditions During Test Drive | | Dry | |
|-----------------------------------|---------------|--------------|--|
| Engine Timing Mechanism | | Timing Chain | |
| Evidence of Cam Belt Replacement | | Yes No Kms | |
| Inspected by: | Gary Adams | | |
| Published by: | Amanda Loader | | |
| Inspection Date: | 24 Nov 2025 | | |

| Cooling performance | / | | |
|--------------------------------|-------------|--------|-------|
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | > | | |
| Noise | / | | |
| Clutch | | | • |
| CV joints | ✓ | | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | / | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | 6 | .0 mm |
| Right front | | 6 | .0 mm |
| Left rear | | 5 | .0 mm |
| Right rear | | 5 | .0 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | / | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | / | | |
| Electrical / Accessories | | | |
| Head lights | / | | |
| Tail lights | V | | |
| Indicators | ✓ | | |
| Dashboard warning lights | V | | |
| Wipers (front & rear) | / | | |
| Window winder FL | > | | |
| Window winder FR | > | | |
| Window winder RL | > | | |
| Window winder RR | > | | |
| Rear view mirrors | > | | |
| Radio (basic test only) | > | | |
| CD (basic test only) | | | • |
| Number of keys | 2 | | |
| Central locking | / | | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | | | / |
| Reversing camera | / | | |
| | | | |

| have read and understood |
|--------------------------|
| this condition guide: |

| N | Δ | M | F |
|---|---|---|---|

SIGNATURE