


| Report ID: | 25,004,457 | Version: | 3 |
|------------|-------------|----------|---|
| Created: | 04 Dec 2025 | | |

| Make: | Subaru | Model: | Forester |
|---------------|-------------|------------------|-------------------|
| Body Style: | suv | Year: | 2022 |
| Rego No.: | PLK183 | Rego Expiry: | 14 Mar 2026 |
| WoF Expiry: | 15 Sep 2026 | Odometer: | 55,641 Kms |
| Good No.: | 25004457 | VIN: | JF2SK9KL5NG083715 |
| Next Service: | 60,000 Kms | Service History: | Yes |

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Windscreen has stone chip

| Conditions During Body Inspection | Dry | | |
|---|-----|--|--|
| Under Carriage and Under Bonnet Inspection Comments | | | |

| Interior Comments | | |
|-------------------|---------|--|
| Seats: | Average | |
| Carpets: | Average | |
| Panels: | Average | |
| Dashboard: | Average | |

General Comments

I have read and understood this condition guide:

Air conditioning and heating systems along with reverse camera working at time of inspection.

| Pond Conditions During Tost Drive | | Dry |
|-----------------------------------|---------------|--------------|
| Road Conditions During Test Drive | | Dry |
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Gary Adams | |
| Published by: | Amanda Loader | |
| Inspection Date: | 26 Nov 2025 | |

| NAME | SIGNATURE |
|------|-----------|

| | ОК | Requires Attention | N/A |
|--------------------------------|----------|-----------------------|----------|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ~ | | |
| Engine performance | / | | |
| Noise | V | | |
| Coolant condition | ~ | | |
| Cooling performance | ~ | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | / | | |
| Noise | / | | |
| Clutch | | | / |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | > | | |
| Hand brake | / | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | 6 | 3.0 mm |
| Right front | | 6 | 6.0 mm |
| Left rear | | 7 | 7.0 mm |
| Right rear | | 5 | 5.0 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | V | | |
| Indicators | ✓ | | |
| Dashboard warning lights | V | | |
| Wipers (front & rear) | | | |
| Window winder FL | / | | |
| Window winder FR | / | | |
| Window winder RL | / | | |
| Window winder RR | / | | |
| Rear view mirrors | / | | |
| Radio (basic test only) | / | | |
| CD (basic test only) | | | / |
| Number of keys | 2 | | |
| Central locking | / | | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | | | / |
| Powersing camera | 4 | 1 | l |