

Report ID:	25,004,627	Version:	1
Created:	26 Nov 2025		

WoF Expiry: 07 Oct 2026 Odometer: 108,014 Kms  Good No.: 25004627 VIN: JTNKN3JE60J503320  Next Service: 116,000 kms Service History: Yes  ote: This report is not a warranty his report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or agnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recomment II mechanical inspection prior to purchase and this can be arranged for an additional charge.  ey  = Scratch R = Rust C = Crack * = Decals W = Significant size Dent PT = Paint defect P = Pin dent SC = Stone Chips  S SC S S S
WoF Expiry: 07 Oct 2026 Odometer: 108,014 Kms  Good No.: 25004627 VIN: JTNKN3JE60J503320  Next Service: 116,000 kms Service History: Yes  lote: This report is not a warranty his report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or iagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommendable mechanical inspection prior to purchase and this can be arranged for an additional charge.  Key  SEC  SSC  SSC  SSC  SSC  SSC  SSC  SS
Good No.: 25004627 VIN: JTNKN3JE60J503320  Next Service: 116,000 kms Service History: Yes  Note: This report is not a warranty  This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or liagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommer ull mechanical inspection prior to purchase and this can be arranged for an additional charge.  Key  S = Scratch R = Rust C = Crack * = Decals W = Significant so Decay Dent PT = Paint defect P = Pin dent SC = Stone Chips  S SC S S
Next Service: 116,000 kms Service History: Yes  Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommend full mechanical inspection prior to purchase and this can be arranged for an additional charge.  Key  S = Scratch R = Rust C = Crack * = Decals W = Significant states and the screen of the prior of the pri
Note: This report is not a warranty  This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommer full mechanical inspection prior to purchase and this can be arranged for an additional charge.  Key  S = Scratch R = Rust C = Crack * = Decals W = Significant SD = Dent PT = Paint defect P = Pin dent SC = Stone Chips  S SC S S S
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips  S SC S S S  S S S S S S S S S S S S S
S SC S R SC S R SC
S R SC   S R SC
Note: some defects and blemishes may not be displayed in the diagram
Body Inspection Comments
Conditions During Body Inspection Dry

	OK	Requires Attention	
Engine	ΟI	Accidon	14/74
Oil level	<b>/</b>	l	
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	<b>'</b>		
Cooling performance	/		
Radiator / Hoses (visual)	_		
Transmission			<u> </u>
Operation	<b>/</b>		
Noise	1		
Clutch	-		
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	<b>/</b>		
Hand brake	1		
Tyres (lowest observed tread d	enth of	tvres)	
Left front	Cpuroi		5.0 mm
Right front			5.0 mm
Left rear			3.0 mm
Right rear			1.0 mm
Spare	Yes		
Suspension			
Suspension performance	<b>/</b>		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	1		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL			
Window winder FR	<b>'</b>		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)	1		
Number of keys	2	I.	
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)			
Reversing camera	1		

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

Air conditioning and heating systems along with reverse camera working at time of inspection.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Amanda Loader	
Inspection Date:	26 Nov 2025	

۱ŀ	nave	read	and	understo	od
th	is co	nditi	on a	uide.	

NAME			