

Basic Condition Guide

•	Report ID: 25,004,643		Version:	2
	Created:	03 Dec 2025		

	ок	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	1		
Engine performance	1		
Noise	1		
Coolant condition	•		
Cooling performance	1		
Radiator / Hoses (visual)			
Transmission		1	
Operation	/		
Noise	1		
Clutch			1
CV joints			-
Wheel bearings	1		
Brakes			
Performance	1		
Hand brake	·		
Tyres (lowest observed tread d	epth of	tvres)	
Left front	Сригог		9.0 mm
Right front			3.0 mm
Left rear			3.0 mm
Right rear			3.0 mm
Spare	Yes		
Suspension	100		
Suspension performance	·/	I	
Steering performance	1		
Shock absorbers	<i>y</i>		
Air Conditioning / Heater			
	/		
Operation Electrical / Accessories			
		l	
Head lights			
Tail lights Indicators	· ·		
Dashboard warning lights	V		
Windowwindor Fl	~		
Window winder FL		-	
Window winder FR	V		
Window winder RL	V		
Window winder RR	V		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	2		L
Number of keys	3	1	
Central locking	•		
Remote locking	•		
Sat. nav. (basic test only)			_
Reversing camera			


Make:	Mazda	Model:	Bt-50
Body Style:	Utility	Year:	2013
Rego No.:	GWG266	Rego Expiry:	02 Jul 2026
WoF Expiry:	14 May 2026	Odometer:	350,442 Kms
Good No.:	25004643	VIN:	MM0UP0YF100154749
Next Service:	357,000 Kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Interior Comments Seats: Average Average Carpets: Panels: Average Dashboard: Average **General Comments**

Air conditioning and heating systems working at time of inspection.

Road Condition	s During Test Drive	Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Amanda Loader	
Inspection Date:	27 Nov 2025	

I have read and understood
this condition guide:

NAME			