

## **Basic Condition Guide**

•	Report ID:	25,004,689	Version:	3
	Created:	19 Dec 2025		

	umer	S Dasi	C Condition Guide	Created:	19 Dec 2025					
Make:	Nissan	Model:	Serena			OK	Requires Attention	N/A		
Body Style:	Wagon	Year:	2012	Engine		OK	Attention	IN/A		
Rego No.:	RJR566	Rego Expiry:	28 Feb 2026	Oil level		·				
WoF Expiry:	26 Aug 2026	Odometer:	16,532 Miles	Smoke & fumes		1				
Good No.: 25004689		VIN:	7AT0DH3FX25068653	Engine performance		1				
Next Service:		Service History:	No	Noise		1				
Note: This report is	not a warranty	Coolant co	ndition	1						
his report is a guide liagnostic testing un	only. Consideration is mad dertaken. The vehicle has b	Cooling pe		1						
ull mechanical inspection prior to purchase and this can be arranged for an additional charge.					Hoses (visual)	1				
Кеу		Transmissi								
	= Rust C = C	Operation 🗸								
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips						1		-		
		s s		Noise		•				
				Clutch				<b>/</b>		
	$\sim$		S SC	CV joints		/				
S SC W				Wheel bearings						
<del>-</del> A	18			Brakes						
1				Performan	ce	/				
				Hand brake	2	/				
s sc				Tyres (lowe	Tyres (lowest observed tread depth of tyres)					
				Left front				4.0 mr		
			SD	Right front		4.0 mm				
				Left rear		4.0 mm				
						4.0 mm				
Note: some defects and blemishes may not be displayed in the diagram						No				
Body Inspecti	on Comments			Suspensio	n					
Headlights fade	ed			Suspension	n performance	1				
				Steering pe	erformance	1				
				Shock abso	orbers	1				
Conditions Dur	ring Body Inspection		Air Conditioning / Heater							
Under Carriag	e and Under Bonnet	Inspection Comm	Operation		1					
No spare wheel	/ inflation device	<del>-</del>		Electrical /	Accessories					
				Head lights	<u> </u>	V				
				Tail lights		1				
Interior Comm	nents			Indicators		1				
Seats:	Average				warning lights	1				
Carpets:	Average			Dashboard warning lights Wipers (front & rear)		1	<del>                                     </del>			
Panels:	Average			Window w		1				
Dashboard: Average				Window w		1		<u> </u>		
General Comr	_		Window w		1	-				
	and heating systems	working at time of			1	-	<u> </u>			
Reverse camera		working at tille Of	поросноп.	Window w		-				
This vehicle only	y shows miles - needs	s software to be ins	talled to change this setting.	Rear view r		/		<del>                                     </del>		
		T-		Radio (basi		/		<u> </u>		
	ns During Test Drive	Dry		CD (basic to				/		
Engine Timing Mechanism Timing Chain					keys	2	1			
Evidence of Cam Belt Replacement Yes No Kms			Central loc	king	/		<u> </u>			
Inspected by:	Gary Adams			Remote loc	king	/				
						II.		1 .		

I have read and understood this condition guide:

Inspection Date: 27 Nov 2025

Amanda Loader

Published by:

NAME

SIGNATURE

Sat. nav. (basic test only)

Reversing camera