

Basic Condition Guide

| Report ID: | 25,004,810 | Version: | 2 |
|------------|-------------|----------|---|
| Created: | 12 Dec 2025 | | |

| Make: | Mitsubishi | Model: | Triton | | ОК | Requires Attention | N/A | |
|----------------------------|---|------------------------------|----------------------------|--|-----|-----------------------|--------|--|
| Body Style: | Utility | Year: | 2012 | Engine | | | | |
| Rego No.: | GFL926 | Rego Expiry: | 30 Jul 2026 | Oil level | V | | | |
| WoF Expiry: | 22 Feb 2026 | Odometer: | 333,510 Kms | Smoke & fumes | 1 | | | |
| Good No.: | 25004810 | VIN: | MMAENKB40BD014349 | Engine performance | 1 | | | |
| Next Service: | 339,000 Kms | Service History: | Yes | Noise | 1 | | | |
| Note: This report is | • | | Coolant condition | 1 | | | | |
| diagnostic testing un | only. Consideration is mad dertaken. The vehicle has b | oeen driven up to 50km | Cooling performance | 1 | | | | |
| | ection prior to purchase an | nd this can be arranged | Radiator / Hoses (visual) | 1 | | | | |
| Key S = Scratch R : | = Rust | Crack *= Dec | als W = Significant scuffs | Transmission | | | | |
| | $\Gamma = \text{Paint defect} P = P$ | | one Chips | Operation | V | | | |
| (2.2.2.11) | | | | Noise | 1 | | | |
| S D SC W | SE | D R SC | | Clutch | 1 | | | |
| | | | | CV joints | 1 | | | |
| | | + | | Wheel bearings | 1 | | | |
| (SCSCW) | | | | Brakes | | <u> </u> | | |
| | | | | Performance | V | | | |
| | | | S R PT SC | Hand brake | 1 | | | |
| S R SC | D | | | Tyres (lowest observed tread depth of tyres) | | | | |
| 4 | | | | Left front | Ť | | 5.0 mm | |
| | | | (Q) | Right front | | (| 6.0 mm | |
| | | | | Left rear | | 8 | 3.0 mm | |
| S D R PT SC | S D | PT SC | | Right rear | | 8 | 3.0 mm | |
| Note: some defects | and blemishes may not be | e displayed in the diag | ram | Spare | Yes | | | |
| Body Inspection | | a a spiayea iii a iie a iiag | | Suspension | | | | |
| , , | | | | Suspension performance | V | | | |
| | | | | Steering performance | 1 | | | |
| | | | | Shock absorbers | 1 | | | |
| Conditions Dur | ing Body Inspection | | Dry | Air Conditioning / Heater | | | | |
| Under Carriag | e and Under Bonnet | t Inspection Com | - | Operation | V | | | |
| | | • | | Electrical / Accessories | | | | |
| | | | | Head lights | V | | | |
| | | | | Tail lights | V | | | |
| Interior Comm | nents | | | Indicators | 1 | | | |
| Seats: | marks | | | Dashboard warning lights | 1 | | | |
| Carpets: | Average | | | Wipers (front & rear) | 1 | | | |
| Panels: | scratches scuffs marks | | | Window winder FL | 1 | | | |
| Dashboard: | scratches | | | Window winder FR | 1 | | | |
| General Comn | nents | | Window winder RL | | | 1 | | |
| Squeaky clutch | | | Window winder RR | | | 1 | | |
| | | | | Rear view mirrors | 1 | | | |
| | | | | Radio (basic test only) | 1 | | | |
| Road Condition | ns During Test Drive | Dry | CD (basic test only) | | | 1 | | |
| Engine Timing | | Cambelt | Number of keys | 1 | 1 | 1 | | |
| | m Belt Replacement | Yes | ✓ No Kms | Central locking | 1 | | | |
| Inspected by: | Gary Adams | L " | | Remote locking | | V | | |
| Published by: | Amanda Loader | | · | Sat. nav. (basic test only) | | <u> </u> | 1 | |
| , | | | | , , | | | | |

I have read and understood this condition guide:

Inspection Date: 04 Dec 2025

NAME

SIGNATURE

Reversing camera