

Basic Condition Guide

•	Report ID:	25,005,015	Version:	1
	Created:	05 Dec 2025		

N/A

5.0 mm 5.0 mm 5.0 mm 5.0 mm

	Jillei	<u> </u>		Created:	05 Dec 2025		
Make:	Toyota	Model:	Corolla			OV	Require
Body Style:	Hatchback	Year:	2017	Engine		OK	Attentio
Rego No.:	KNU770	Rego Expiry:	30 Nov 2026	- Oil level		· ·	
WoF Expiry:	20 Jan 2026	Odometer:	204,403 Kms	Smoke & f	umes	1	
Good No.:	25005015	VIN:	JTNKU3JE00J563130	Engine pe		1	-
Next Service:	212,000 Kms	Service History:	Yes	Noise	Homiance	1	
Note: This report is	not a warranty			Coolant co	ndition	1	
diagnostic testing un	dertaken. The vehicle has b	een driven up to 50km/l	arts have not been dismantled or n from cold. The Vendor recommends a		erformance	1	-
ull mechanical inspe	ction prior to purchase and	d this can be arranged fo	or an additional charge.		Hoses (visual)	1	
Key				Transmiss			
	= Rust C = C = Paint defect P = Pi		3	Operation		·	
		Truchi SC = Stor	ic criips	Noise		1	-
PT SC	DI	R SC D R SC	SC	Clutch			-
				CV joints		1	
	$(0)_{\mathbb{Z}}$		(\bigcirc)	Wheel bearings			
SW A				Brakes	93		<u> </u>
M	Pr II			Performan	nce	V	
R SC					re	1	
D R SC	D D			Tyres (lowest observed tread depth of tyres)			
				Left front			7
			(Q) sc	Right fron	 t		
				Left rear			
PT SC	S	SC	R SC	Right rear			
Note: some defects a	and blemishes may not be	displayed in the diagra	m	Spare		Yes	
Body Inspection				Suspension	on		
Headlights fade	d. Both front fenders I	have paint peeling	off.	Suspensio	n performance	1	
				Steering p	erformance		~
				Shock abs	orbers	1	
Conditions During Body Inspection Dry					Air Conditioning / Heater		
Under Carriage and Under Bonnet Inspection Comments				Operation		1	
				Electrical	/ Accessories		
				Head light	S	/	
				Tail lights		1	
Interior Comm	ents			Indicators		1	
Seats: Average			Dashboard	d warning lights	1		
Carpets:	Average			Wipers (fro		1	

Interior Comments			
Seats:	Average		
Carpets:	Average		
Panels:	Average		
Dashboard:	Average		
General Comments			

1 out of 2 keys remote not wworking.

AC and heating systems good temperature along with reversing camera working at time of inspection.

Wheel alignment required, steering wheel off centre, pulling right.

	<u> </u>			
Road Condition	s During Test Drive	Dry		
Engine Timing N	Mechanism	Timing Chain		
Evidence of Can	Evidence of Cam Belt Replacement		No	Kms
Inspected by:	Finlay Lemmens			
Published by:	Amanda Loader			
Inspection Date:	05 Dec 2025			

I have read and understood
this condition guide:

NAME			

SIGNATURE			

1

1

1

1

2

<u>ノ</u>

Window winder FL
Window winder FR

Window winder RL

Window winder RR

Rear view mirrors
Radio (basic test only)

CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only)
Reversing camera