

•	Report ID: 25,005,247		Version:	1
	Created:	12 Dec 2025		

		ОК	Requires Attention	N/A
	Engine			
6	Oil level	V		
S	Smoke & fumes	1		
0J502497	Engine performance	/		
	Noise	1		
lismantled or	Coolant condition	1		
ndor recommends a arge.	Cooling performance	/		
iige.	Radiator / Hoses (visual)	/		
Significant scuffs	Transmission			
Significant scans	Operation	V		
	Noise	1		
	Clutch			1
S SC	CV joints	1		
550	Wheel bearings	1		
	Brakes			
	Performance	V		
S R SC	Hand brake	1		
HH.	Tyres (lowest observed tread	depth of	tyres)	
	Left front			5.0 mr
	Right front		5	5.0 mr
	Left rear		3	3.0 mr
	Right rear			1.0 mr
	Spare	Yes		
	Suspension			
	Suspension performance	V		
	Steering performance	1		
	Shock absorbers	1		
	Air Conditioning / Heater			
	Operation	V		
	Electrical / Accessories			
	Head lights	V		
	Tail lights	1		
	Indicators	1		
	Dashboard warning lights	1		
	Wipers (front & rear)	1		
	Window winder FL	1		
	Window winder FR	1		
	Window winder RL	1		
g at time of	Window winder RR	1		
-	Rear view mirrors	1		
	Radio (basic test only)	1		
	CD (basic test only)	-		1
	Number of keys	2	I	
Kms	Central locking	- -		
1(11)3	Remote locking	1		
	Sat. nav. (basic test only)			_
	Reversing camera	1		
	g carriera			

O To	Jrner	S Basi	c Condition Guide		
Make:	Toyota	Model:	Corolla		
Body Style:	Hatchback	Year:	2017		
Rego No.:	KNK260	Rego Expiry:	21 May 2026		
WoF Expiry:	20 Jun 2026	Odometer:	108,386 Kms		
Good No.:	25005247	VIN:	JTNKN3JE70J502497		
Next Service:	112,000 Kms	Service History:	Yes		
diagnostic testing und full mechanical inspe	dertaken. The vehicle has be ction prior to purchase and	een driven up to 50km/b d this can be arranged f	h from cold. The Vendor recommends a or an additional charge.		
	Rust $C = C$				
D = Dent PT	= Paint defect $P = Pi$	n dent SC = Sto	ne Chips		
S R PT SC	S	SC S R SC			
S R PT SC S S C S R SC S R SC S R SC					
	s	SC S R SC			
Note: some defects a	nd blemishes may not be	displayed in the diagra	am		
Body Inspection	on Comments				
Paint faded and	defects in multiple ar	eas			

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

General Comments

Air conditioning and heating systems along with reverse camera work inspection.

Road Condition	s During Test Drive	Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Amanda Loader	
Inspection Date:	12 Dec 2025	

I have read and understood	k
this condition quide	

NAME			