


Make:	Hyundai	Model:	Santa FE
Body Style:	SUV	Year:	2021
Rego No.:	NYP612	Rego Expiry:	22 Apr 2026
WoF Expiry:	23 Dec 2025	Odometer:	86,886 Kms
Good No.:	25005711	VIN:	KMHS381MMMU377417
Next Service:	93,000 Kms	Service History:	Yes

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

#### Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

#### Body Inspection Comments

All tyres including spare are bald and require replacement, casing and tabs are showing through.

Spare tyre is currently on LF - Different tyre size

Tyre in boot - Fail

Conditions During Body Inspection      Wet

#### Under Carriage and Under Bonnet Inspection Comments

#### Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

#### General Comments

TPMS light on,  
 Centre rear view mirror loose.  
 AC and heating systems good temperature along with reversing camera and sat nav working at time of inspection.

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Finlay Lemmens
Published by:	Amanda Loader
Inspection Date:	29 Dec 2025

I have read and understood  
 this condition guide:

NAME \_\_\_\_\_

Report ID:	25,005,711	Version:	2
Created:	14 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front		7 mm	
Right front		1.0 mm	
Left rear		4 mm	
Right rear		2.5 mm	
Spare		No	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance			✓
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights			✓
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		

SIGNATURE \_\_\_\_\_